

BridgeX® Firmware fw-BridgeX

Rev 8.3.3160

www.mellanox.com

NOTE:

THIS INFORMATION IS PROVIDED BY MELLANOX FOR INFORMATIONAL PURPOSES ONLY AND ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE FOR ANY DIRECT, INDIRECT, INCIDENTAL, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES (INCLUDING, BUT NOT LIMITED TO, PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY OUT OF THE USE OF THIS HARDWARE, EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies 350 Oakmead Parkway Sunnyvale, CA 94085 U.S.A. www.mellanox.com

Tel: (408) 970-3400 Fax: (408) 970-3403 PO Box 586 Hermon Building Yokneam 20692 Israel

Mellanox Technologies, Ltd.

Tel: +972-4-909-7200 Fax: +972-4-959-3245

© Copyright 2009. Mellanox Technologies, Inc. All Rights Reserved.

Mellanox®, ConnectX®, InfiniBlast®, InfiniBridge®, InfiniHost®, InfiniRISC®, InfiniScale®, and InfiniPCI® are registered trademarks of Mellanox Technologies, Ltd.

BridgeX and Virtual Protocol Interconnect are trademarks of Mellanox Technologies, Ltd.

All other marks and names mentioned herein may be trademarks of their respective companies.

2 Mellanox Technologies Document Number:

Table of Contents

Table of Contents					
Chapter 1	Introduction	4			
Chapter 2	Firmware fw-BridgeX Compatibility	4			
Chapter 3	Changes and New Features				
_	3.1 BridgeX Firmware v8.3.3160				
	3.2 BridgeX Firmware v8.3.3000	5			
Chapter 4	Bug Fixes.	6			
Chapter 5	Known Issues	7			

Rev 8.3.3160 Introduction

1 Introduction

These are the release notes for the BridgeX® gateway firmware, fw-BridgeX Rev 8.3.3160. This firmware supports the following protocols:

- Ethernet over InfiniBand (EoIB)
- Fibre Channel over Ethernet (FCoE)
- Fibre Channel over InfiniBand (FCoIB)
- Ethernet to Ethernet (PHyX®)

Note: After burning the new firmware, reboot your system to activate the new firmware. Failing to do so will result in an error when running the RUN FW command.

2 Firmware fw-BridgeX Compatibility

Firmware fw-BridgeX Rev 8.3.3160 is compatible with:

- BridgeX Programmer's Reference Manual (PRM), Rev 0.90 or later
- Mellanox BridgeX Management (BXM) software version 1.3.6-0

3 Changes and New Features

3.1 BridgeX Firmware v8.3.3160

BridgeX firmware v8.3.3160 does not contain any new changes/features.

3.2 BridgeX Firmware v8.3.3000

- Added VL separation support
- Added PhyX® command interface
- · Added ARP proxy lookup mode
- Added anti-spoofing support for multicast Packets
- Added RSS configuration
- Made Ethernet link change events configurable
- Added Ethernet link change events support in managed PhyX® mode
- Added link policy reflection in PhyX® mode
- Added module rate select configuration in Fibre Channel port (access by i2c or GPIO).
- Added external port module state change
- Added port drop counters
- Added counters per priority port
- Added support to XFI detection in the parallel detect.
- Added reset counters policy
- Added MTU configuration
- The chips are now presented as 2 port IB with a single node guid

Rev 8.3.3160 Bug Fixes

4 Bug Fixes

Table 1 - Bug Fixes

Index	Issue	Description	Found in FW Version	Fixed in FW Version
1.	Cable plugging issue	Possible link failure upon cable plugging.	8.3.0000	8.3.3160
2.	Device link up issues	The device might link up in SDR vs. DDR capable devices.	8.3.0000	8.3.3160
3.	SGMII link issues	Upon protocol change the SGMII link might fail.	8.3.0000	8.3.3160

5 Known Issues

The following table describes known issues and possible workarounds.

Index	Description	Possible Workaround
1.	Fibre Channel link resets in apha state.	
2.	Dcbx is not supported in this version.	
3.	The firmware does not indicate the actual capability of the Fibre Channel module speed.	
4.	The FCoE protocol indicator LEDs of external ports is not flouncing.	
5.	Mapping of sl2vl can be performed only when the IB logical link is down.	