



Connect. Accelerate. Outperform.™

Mellanox ConnectX-3 Firmware Release Notes

Rev 2.35.5100

NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT (“PRODUCT(S)”) AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES “AS-IS” WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER'S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies
 350 Oakmead Parkway Suite 100
 Sunnyvale, CA 94085
 U.S.A.
www.mellanox.com
 Tel: (408) 970-3400
 Fax: (408) 970-3403

© Copyright 2015. Mellanox Technologies. All Rights Reserved.

Mellanox®, Mellanox logo, BridgeX®, CloudX logo, Connect-IB®, ConnectX®, CoolBox®, CORE-Direct®, GPUDirect®, InfiniHost®, InfiniScale®, Kotura®, Kotura logo, Mellanox Federal Systems®, Mellanox Open Ethernet®, Mellanox ScalableHPC®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, Open Ethernet logo, PhyX®, SwitchX®, TestX®, The Generation of Open Ethernet logo, UFM®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

Accelio™, CyPU™, FPGADirect™, HPC-X™, InfiniBridge™, LinkX™, Mellanox Care™, Mellanox CloudX™, Mellanox Multi-Host™, Mellanox NEO™, Mellanox PeerDirect™, Mellanox Socket Direct™, Mellanox Spectrum™, NVMeDirect™, StPU™, Spectrum logo, Switch-IB™, Unbreakable-Link™ are trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

Table of Contents

Chapter 1	Overview	6
1.1	Supported Devices	6
1.2	Supported Cables and Modules	7
1.2.1	Tested Cables and Modules	7
1.3	Tested Switches	15
1.4	Tools, Switch Firmware and Driver Software	18
1.5	Supported FlexBoot	18
1.6	Revision Compatibility	18
1.7	Firmware Burning Notes	19
Chapter 2	Firmware Rev 2.35.5100 Changes and New Features	20
Chapter 3	Known Issues	21
Chapter 4	Bug Fixes History	24
Chapter 5	Firmware Changes and New Feature History	40
Chapter 6	Flexboot Changes and New Features	45

List of Tables

Table 1:	Release Update History	5
Table 2:	Supported PSIDs	6
Table 3:	Tested Cables and Modules	7
Table 4:	Tested Switches	15
Table 5:	Tools, Switch Firmware and Driver Software	18
Table 6:	Supported FlexBoot	18
Table 7:	Firmware Rev 2.35.5100 Changes and New Features	20
Table 8:	Known Issues	21
Table 9:	Fixed Bugs List	24
Table 10:	Firmware Changes and New Feature History	40
Table 11:	FlexBoot Changes and New Feature	45

Release Update History

Table 1 - Release Update History

Release	Date	Description
2.35.5100	November 25th, 2015	Added the following OPNs: <ul style="list-style-type: none">• MCX341A-XCG• MCX342A-XCC
	October 25th, 2015	Added Known Issue #25 to Section 3, “Known Issues” , on page 21
	October 06th, 2015	Updated Section 4, “Bug Fixes History” , on page 24 . added SR-IOV security bug fix.
	September 10th, 2015	Initial version

1 Overview

These are the release notes for the ConnectX®-3 adapters firmware Rev 2.35.5100. This firmware supports the following protocols:

- InfiniBand – SDR, DDR, QDR, FDR10, FDR
- Ethernet - 1GigE, 10GigE, 40GigE and 56GigE¹
- PCI Express 3.0, supporting backwards compatibility for v2.0 and v1.1

1.1 Supported Devices

This firmware supports the devices and protocols listed in [Table 2](#).

Table 2 - Supported PSIDs (Sheet 1 of 2)

Device Part Number	PSID	Device Name
MCX311A-XCAT	MT_1170110023	ConnectX®-3 EN network interface card, 10GbE, single-port SFP+, PCIe3.0 x4 8GT/s, tall bracket, RoHS R6
MCX312A-XCBT	MT_1080110023	ConnectX®-3 EN network interface card, 10GbE, dual-port SFP+, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
	MT_1080120023	
MCX312B-XCBT	MT_1200110023	ConnectX®-3 EN network interface card, 10GbE, dual-port SFP+, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
	MT_1200210023	
MCX313A-BCBT	MT_1060110023	ConnectX®-3 EN network interface card, 40/56GbE, single-port QSFP, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
	MT_1060140023	
MCX314A-BCBT	MT_1090110023	ConnectX®-3 EN network interface card, 40/56GbE, dual-port QSFP, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX353A-FCBT	MT_1100120019	ConnectX®-3 VPI adapter card, single-port QSFP, FDR IB (56Gb/s) and 40/56GbE, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX353A-QCBT	MT_1060110018	ConnectX®-3 VPI adapter card; single-port QSFP; QDR IB (40Gb/s) and 10GigE; PCIe3.0 x8 8GT/s; RoHS R6
MCX353A-TCBT	MT_1100110028	ConnectX®-3 VPI adapter card, single-port QSFP, FDR10 IB (40Gb/s) and 10GbE, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX354A-FCBT	MT_1090110019	ConnectX®-3 VPI adapter card, dual-port QSFP, FDR IB (56Gb/s) and 40/56GbE, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
	MT_1090120019	

1. 56 GbE is a Mellanox propriety link speed and can be achieved while connecting a Mellanox adapter cards to Mellanox SX10XX switch series or connecting a Mellanox adapter card to another Mellanox adapter card.

Table 2 - Supported PSIDs (Sheet 2 of 2)

Device Part Number	PSID	Device Name
MCX354A-QCBT	MT_1090110018	ConnectX®-3 VPI adapter card, dual-port QSFP, QDR IB (40Gb/s) and 10GbE, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX354A-TCBT	MT_1090110028	ConnectX®-3 VPI adapter card, dual-port QSFP, QDR IB (40Gb/s) and 10GbE, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX342A-XCCN	MT_1680110023	ConnectX®-3 EN network interface card for OCP, 10GbE, dual-port SFP+, PCIe3.0 x8, IPMI disabled, no bracket, RoHS R6
MCX341A-XCGN	MT_1270114023	ConnectX®-3 EN network interface card for OCP, 10GbE, single-port SFP+, PCIe3.0 x8, IPMI and NC-SI support, no bracket, RoHS R6

1.2 Supported Cables and Modules

Please refer to the LinkX™ Cables and Transceivers web page (www.mellanox.com -> Products -> Cables and Transceivers) for the list of supported cables.

1.2.1 Tested Cables and Modules

Table 3 - Tested Cables and Modules (Sheet 1 of 9)

Speed	OPN #	Description	Vendor
NA	MAM1Q00A-QSA	MELLANOX QSFP TO SFP+ ADAPTER	MELLANOX
1 GB/S	453151-B21	HP BLc VC 1Gb SX SFP Opt Kit	HP
1 GB/S	453154-B21	HP BLc VC 1Gb RJ-45 SFP Opt Kit	HP
1 GB/S	MC3208011-SX	MELLANOX OPTICAL MODULE ETH 1GBE 1GB/S SFP LC-LC SX 850NM UP TO 500M	MELLANOX
1 GB/S	MC3208411-T	MELLANOX MODULE ETH 1GBE 1GB/S SFP BASE-T UP TO 100M	MELLANOX
10GB/S	CAB-SFP-SFP-1M	passive copper cable, SFP+, 10 Gb/s, 1m	Arista
10GB/S	CAB-SFP-SFP-2M	passive copper cable, SFP+, 10 Gb/s, 2m	Arista
10GB/S	CAB-SFP-SFP-3M	passive copper cable, SFP+, 10 Gb/s, 3m	Arista
10GB/S	CAB-SFP-SFP-5M	passive copper cable, SFP+, 10 Gb/s, 5m	Arista
10GB/S	XDL-TWX0101	Brocade passive copper cable, SFP+, 10 Gb/s, 1m	Brocade
10GB/S	XDL-TWX0301	Brocade passive copper cable, SFP+, 10 Gb/s, 3m	Brocade
10GB/S	XDL-TWX0501	Brocade passive copper cable, SFP+, 10 Gb/s, 5m	Brocade

Table 3 - Tested Cables and Modules (Sheet 2 of 9)

Speed	OPN #	Description	Vendor
10GB/S	Cisco SFP-H10GB-CU1M	Cisco SFP+ cable	Cisco
10GB/S	Cisco SFP-H10GB-CU3M	Cisco SFP+ cable	Cisco
10GB/S	Cisco SFP-H10GB-CU5M	Cisco SFP+ cable	Cisco
10GB/S	MC2309124-007	QSFP-4SFP10G	Cisco
10GB/S	SFP-10G-SR	CISCO 10GBASE-SR SFP Module	Cisco
10GB/S	MC2309124-007	QSFP-4SFP10G	Cisco
10GB/S	0NWGTV	SFP+ to SFP+ copper cable 1M	Dell
10GB/S	0C4D08	SFP+ to SFP+ copper cable 1M	Dell
10GB/S	0V250M	SFP+ to SFP+ copper cable 1M	Dell
10GB/S	0NMMT9	SFP+ to SFP+ copper cable 1M	Dell
10GB/S	053HVN	SFP+ to SFP+ copper cable 3M	Dell
10GB/S	05CWK6	SFP+ to SFP+ copper cable 3M	Dell
10GB/S	00F1VT9	SFP+ to SFP+ copper cable 3M	Dell
10GB/S	00358VV	SFP+ to SFP+ copper cable 5M	Dell
10GB/S	05CN56	SFP+ to SFP+ copper cable 5M	Dell
10GB/S	0V492M	SFP+ to SFP+ copper cable 5M	Dell
10GB/S	0W25W9	SFP+ to SFP+ copper cable 5M	Dell
10GB/S	0J90VN	40GbE QSFP+ to QSFP+ copper cable 5M	Dell
10GB/S	TCPM2	QSFP+ to 4xSFP+ copper cable 1M	Dell
10GB/S	27GG5	QSFP+ to 4xSFP+ copper cable 3M	Dell
10GB/S	P8T4W	QSFP+ to 4xSFP+ copper cable 5m	Dell
10GB/S	0WTRD1	Dell 10Gb SR SFP+ Opt	Dell
10GB/S	C4D08	Force 10passive copper cable, SFP+, 10 Gb/s, 1m	Force10
10GB/S	53HVN	Force 10passive copper cable, SFP+, 10 Gb/s, 3m	Force10
10GB/S	5CN56	Force 10passive copper cable, SFP+, 10 Gb/s, 5m	Force10
10GB/S	J9281B	HP X242 10G SFP+ to SFP+ 1m Direct Attach Copper Cable	HP
10GB/S	J9283B	HP X242 10G SFP+ SFP+ 3m DAC Cable	HP
10GB/S	J9285B	HP X242 10G SFP+ SFP+ 7m DAC Cable	HP

Table 3 - Tested Cables and Modules (Sheet 3 of 9)

Speed	OPN #	Description	Vendor
10GB/S	JD096B	HP X240 10G SFP+ SFP+ 1.2m DAC Cable	HP
10GB/S	JD095B	HP X240 10G SFP+ SFP+ 0.65m DAC Cable	HP
10GB/S	JD097B	HP X240 10G SFP+ SFP+ 3m DAD Cable	HP
10GB/S	JD096C	HP X240 10G SFP+ SFP+ 1.2m DAC Cable	HP
10GB/S	JD095C	HP X240 10G SFP+ SFP+ 0.65m DAC Cable	HP
10GB/S	JD097C	HP X240 10G SFP+ SFP+ 3m DAD Cable	HP
10GB/S	487649-B21	HP BLc SFP+ .5m 10GbE Copper Cable	HP
10GB/S	487652-B21	HP BLc SFP+ 1m 10GbE Copper Cable	HP
10GB/S	487655-B21	HP BLc SFP+ 3m 10GbE Copper Cable	HP
10GB/S	537963-B21	HP BLc SFP+ 5m 10GbE Copper Cable	HP
10GB/S	487658-B21	HP BLc SFP+ 7m 10GbE Copper Cable	HP
10GB/S	AP784A	HP 3m C-series Passive Copper SFP+ Cable	HP
10GB/S	AP785A	HP 5m C-series Passive Copper SFP+ Cable	HP
10GB/S	AP818A	HP 1m B-series Active Copper SFP+ Cable	HP
10GB/S	AP819A	HP 3m B-series Active Copper SFP+ Cable	HP
10GB/S	455883-B21	HP BLc 10Gb SR SFP+ Opt	HP
10GB/S	455886-B21	HP BLc 10Gb LR SFP+ Opt	HP
10GB/S	J9150A	HP X132 10G SFP+ LC SR Transceiver	HP
10GB/S	J9151A	HP X132 10G SFP+ LC LR Transceiver	HP
10GB/S	AJ839A	HP 50m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	AJ838A	HP 30m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	AJ837A	HP 15m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	AJ836A	HP 5m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	AJ834A	HP 1m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	AJ833A	HP 0.5m Multi-mode OM3 LC/LC FC Cable	HP
10GB/S	JG329A	HP X240 40G QSFP+ to 4x10G SFP+ 1m	HP
10GB/S	JG330A	HP X240 40G QSFP+ to 4x10G SFP+ 3m	HP
10GB/S	JG331A	HP X240 40G QSFP+ to 4x10G SFP+ 5m	HP
10GB/S	JD095C	HP X240 10G SFP+ SFP+ 0.65m DAC Cable	HP
10GB/S	90Y9425-N28500A	IBM-Amphenol SFP+ 1m	IBM

Table 3 - Tested Cables and Modules (Sheet 4 of 9)

Speed	OPN #	Description	Vendor
10GB/S	46K6184-L36836B	IBM-Amphenol SFP+ 5m	IBM
10GB/S	46K6183-L36836B	IBM-Amphenol SFP+ 3m	IBM
10GB/S	44X1371-N31295E	IBM-Amphenol SFP+ 7m	IBM
10GB/S	95Y1634-N31295E	IBM SFP+ to SFP+ copper cable 5M	IBM
10GB/S	44x1368-N31295E	IBM SFP+ to SFP+ copper cable 0.5M	IBM
10GB/S	46K6182-L36836B	IBM SFP+ to SFP+ copper cable 1M	IBM
10GB/S	46K6183-L36836B	IBM SFP+ to SFP+ copper cable 3M	IBM
10GB/S	46K6184-L36836B	IBM SFP+ to SFP+ copper cable 5M	IBM
10GB/S	QFX-SFP-DAC-1M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 1 m	Juniper
10GB/S	QFX-SFP-DAC-3M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 3 m	Juniper
10GB/S	QFX-SFP-DAC-5M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 5 m	Juniper
10GB/S	740-021308	Juniper 10GE SFP+ module	Juniper
10GB/S	MC2309124-004	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 4M	MELLANOX
10GB/S	MC2309124-005	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 5M	MELLANOX
10GB/S	MC2309124-006	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 6M	MELLANOX
10GB/S	MC2309124-007	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 7M	MELLANOX
10GB/S	MC2309130-001	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 1M	MELLANOX
10GB/S	MC2309130-002	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 2M	MELLANOX
10GB/S	MC2309130-003	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 3M	MELLANOX
10GB/S	MC2309130-00A	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S QSFP TO SFP+ 0.5M	MELLANOX
10GB/S	MC2609125-004	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 4M	MELLANOX

Table 3 - Tested Cables and Modules (Sheet 5 of 9)

Speed	OPN #	Description	Vendor
10GB/S	MC2609125-005	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 5M	MELLANOX
10GB/S	MC2609130-001	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 1M	MELLANOX
10GB/S	MC2609130-002	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 2M	MELLANOX
10GB/S	MC2609130-003	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 3M	MELLANOX
10GB/S	MC2609130-0A1	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 1.5M	MELLANOX
10GB/S	MC3309124-004	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 4M	MELLANOX
10GB/S	MC3309124-005	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 5M	MELLANOX
10GB/S	MC3309124-006	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 6M	MELLANOX
10GB/S	MC3309124-007	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 7M	MELLANOX
10GB/S	MC3309124-0A3	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 3.5M	MELLANOX
10GB/S	MC3309130-001	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 1M	MELLANOX
10GB/S	MC3309130-002	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 2M	MELLANOX
10GB/S	MC3309130-003	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 3M	MELLANOX
10GB/S	MC3309130-00A	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 0.5M	MELLANOX
10GB/S	MC3309130-0A1	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 1.5M	MELLANOX
10GB/S	MC3309130-0A2	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GB/S SFP+ 2.5M	MELLANOX
10GB/S	MFM1T02A-LR	Mellanox optical module, 1310nm, LR up to 10km	MELLANOX

Table 3 - Tested Cables and Modules (Sheet 6 of 9)

Speed	OPN #	Description	Vendor
10GB/S	MFM1T02A-SR	Mellanox optical module, 850nm, SR up to 300m	MELLANOX
40GB/S	40GbE QSFP+ to QSFP	QSFP+ copper cable 3M	Arista
40GB/S	40GbE QSFP+ to QSFP	QSFP+ copper cable 5M	Arista
40GB/S	QSFP-H40G-CU1M	Cisco QSFP 40GbE cable	Cisco
40GB/S	QSFP-H40G-CU3M	Cisco QSFP 40GbE cable	Cisco
40GB/S	QSFP-H40G-CU5M	Cisco QSFP 40GbE cable	Cisco
40GB/S	QSFP-40G-SR4	CISCO 40G QSFP Module	Cisco
40GB/S	05NP8R	40GbE QSFP+ to QSFP+ copper cable 1M	Dell
40GB/S	00FC6KV	40GbE QSFP+ to QSFP+ copper cable 3M	Dell
40GB/S	0RF2MY	Dell 40GbB QSFP module	Dell
40GB/S	10093084-200AHFLF	FCI QSFP 0.75m 40GbE cable	FCI
40GB/S	10093084-2005HFLF	FCI QSFP 0.5m 40GbE cable	FCI
40GB/S	10093084-2010HFLF	FCI QSFP 1m 40GbE cable	FCI
40GB/S	NWGTV	Force 10 passive copper cable, QSFP, 40 Gb/s, 1m	Force10
40GB/S	V492M	Force 10 passive copper cable, QSFP, 40 Gb/s, 5m	Force10
40GB/S	GP-QSFP-40GE-1SR	Force10 - Dell 40GbB QSFP module	Force10
40GB/s	JG325B	HP X140 40G QSFP+ MPO SR4 Transceiver	HP
40GB/S	JG325A	HP X140 40G QSFP+ MPO SR4 Transceiver	HP
40GB/S	JG326A	HP X240 40G QSFP+ QSFP+ 1m DAC Cable	HP
40GB/S	JG327A	HP X240 40G QSFP+ QSFP+ 3m DAC Cable	HP
40GB/S	JG328A	HP X240 40G QSFP+ QSFP+ 5m DAC Cable	HP
40GB/S	00D5802-N13445C	IBM 40GbE QSFP+ to QSFP+ copper cable 1M	IBM
40GB/S	BN-QS-QS-CBL-3M	IBM 40GbE QSFP+ to QSFP+ copper cable 3M	IBM
40GB/S	BN-QS-QS-CBL-5M	IBM 40GbE QSFP+ to QSFP+ copper cable 5M	IBM
40GB/S	MC2210126-004	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GB/S QSFP 4M	MELLANOX
40GB/S	MC2210126-005	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GB/S QSFP 5M	MELLANOX

Table 3 - Tested Cables and Modules (Sheet 7 of 9)

Speed	OPN #	Description	Vendor
40GB/S	MC2210128-003	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GB/S QSFP 3M	MELLANOX
40GB/S	MC2210130-001	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GB/S QSFP 1M	MELLANOX
40GB/S	MC2210130-002	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GB/S QSFP 2M	MELLANOX
40GB/S	MC2210310-XXX	MELLANOX ACTIVE FIBER CABLE ETH 40GBE 40GB/S QSFP from 3M up to 100M	MELLANOX
40GB/S	MC2210411-SR4L	MELLANOX OPTICAL MODULE 40GB/S QSFP MPO 850NM UP TO 30M	MELLANOX
DDR	MC1204128-001	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 1M	MELLANOX
DDR	MC1204128-003	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 3M	MELLANOX
DDR	MC1204128-005	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 5M	MELLANOX
DDR	MC1204130-002	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 2M	MELLANOX
FDR	038-004-066-01	EMC FDR QSFP+ to QSFP+ copper cable 2M	EMC FDR QSFP
FDR	038-004-067-01	EMC FDR QSFP+ to QSFP+ copper cable 3M	EMC FDR QSFP
FDR	038-900-027-01	EMC FDR QSFP+ to QSFP+ copper cable 5M	EMC FDR QSFP
FDR	038-900-030-01	EMC FDR QSFP+ to QSFP+ copper cable 8M	EMC FDR QSFP
FDR	038-004-236-01	FDR QSFP+ to QSFP+ copper cable 0.5m	EMC FDR QSFP
FDR	038-004-065-01	EMC FDR QSFP+ to QSFP+ copper cable 1M	EMC FDR QSFP
FDR	038-004-069-01	EMC FDR QSFP+ to QSFP+ copper cable 5M	EMC FDR QSFP
FDR	MC2207126-004	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 4M	MELLANOX
FDR	MC2207128-003	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 3M	MELLANOX
FDR	MC2207128-0A2	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 2.5M	MELLANOX

Table 3 - Tested Cables and Modules (Sheet 8 of 9)

Speed	OPN #	Description	Vendor
FDR	MC2207130-001	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 1M	MELLANOX
FDR	MC2207130-002	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 2M	MELLANOX
FDR	MC2207130-00A	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 0.5M	MELLANOX
FDR	MC2207130-0A1	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 1.5M	MELLANOX
FDR	MC2207310-XXX-E	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M	MELLANOX
FDR	MC2207310-XXX-T	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M	MELLANOX
FDR	MC2207312-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 300M	MELLANOX
FDR	MC220731V-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M	MELLANOX
FDR	MC2207411-SR4L	MELLANOX OPTICAL MODULE IB FDR 56GB/S QSFP MPO 850NM UP TO 30M	MELLANOX
FDR10	MC2206128-004	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 4M	MELLANOX
FDR10	MC2206128-005	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 5M	MELLANOX
FDR10	MC2206130-001	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 1M	MELLANOX
FDR10	MC2206130-002	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 2M	MELLANOX
FDR10	MC2206130-003	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 3M	MELLANOX
FDR10	MC2206130-00A	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GB/S QSFP 0.5M	MELLANOX
FDR10	MC2206310-XXX-E	MELLANOX ACTIVE FIBER CABLE IB QDR/ FDR10 40GB/S QSFP from 3M up to 100M	MELLANOX
FDR10	MC2206310-XXX-T	MELLANOX ACTIVE FIBER CABLE IB QDR/ FDR10 40GB/S QSFP from 3M up to 100M	MELLANOX
FDR10	MC2206310-XXX-F	MELLANOX ACTIVE FIBER CABLE IB QDR/ FDR10 40GB/S QSFP from 3M up to 100M	MELLANOX
FDR10	MC2206310-300-L	MELLANOX ACTIVE FIBER CABLE IB QDR/ FDR10 40GB/S QSFP 300M	MELLANOX

Table 3 - Tested Cables and Modules (Sheet 9 of 9)

Speed	OPN #	Description	Vendor
FDR10	MC2210411-SR4	MELLANOX OPTICAL MODULE 40GB/S QSFP MPO 850NM UP TO 100M	MELLANOX
FDR10	MC2210411-SR4E	MELLANOX OPTICAL MODULE 40GB/S QSFP MPO 850NM UP TO 300M	MELLANOX
FDR10	MFS4R12CB-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 40GB/S QSFP from 3M up to 100M	MELLANOX
QDR	MC2206125-007	MELLANOX PASSIVE COPPER CABLE IB QDR 40GB/S QSFP 7M	MELLANOX
QDR	MC2206126-006	MELLANOX PASSIVE COPPER CABLE IB QDR 40GB/S QSFP 6M	MELLANOX

1.3 Tested Switches

Table 4 - Tested Switches (Sheet 1 of 4)

Speed	OPN # /Name	Description	Vendor
10/40Gb/s	7050Q	16-port 40Gb Switch	Arista
10/40Gb/s	7050S	48-port 10Gb/40Gb Switch	Arista
40GbE	7050QX	32-port 40Gb Switch	Arista
10Gb/s	Brocade 8000	Brocade 10GB ETH switch	Brocade
10/40Gb/s	3064	48-port 10Gb/40Gb Switch	Cisco
10Gb/s	5548	Cisco 10GB ETH switch	Cisco
40GbE	3016	Cisco 40GB ETH switch	Cisco
40GbE	3132Q	Cisco 40GB ETH switch	Cisco
10/40Gb/s	S5000	10GbE switch	Dell
10Gb/s	8024F	10GbE switch	Dell
10Gb/s	8132F	10GbE switch	Dell
10Gb/s	8164F	10GbE switch	Dell
1Gb/s	7024F	1/10GbE switch	Dell
40GbE	S6000	32-port 40Gb Switch	Dell
10/40Gb/s	S4810P-AC	48-port 10Gb/40Gb Switch	Force 10
10Gb/s	Fujitsu 10GbE	Ethernet Switch 24 ports, 20xCX4 and 4xQSFP	Fujitsu
10/40Gb/s	ASF5900	HP 10GB ETH switch	HP

Table 4 - Tested Switches (Sheet 2 of 4)

Speed	OPN # /Name	Description	Vendor
10Gb/s	HP ProCurve 6600-24XG	24-port 10GbE switch	HP
10GbE	516733-B21	HP ProCurve 6120XG 10GbE Ethernet Blade Switch	HP
10GbE	6125XLG Blade Switch	HP 6125XLG 10/40G Ethernet Blade Switch	HP
10GbE	538113-B21	HP 10GbE Pass-Through Module (PTM)	HP
1Gb/s	2810-24G	HP 1GB ETH switch	HP
1GbE	3020X	Cisco Catalyst 3020X 1GbE switch blade	HP
1GbE	3020	Cisco Catalyst 3020 1GbE switch blade	HP
1GbE	438030-B21	HP 1GbE switch module - GbE2c Layer 2/3 Ethernet Blade Switch	HP
1GbE	6120G	HP ProCurve 6120G/XG 1GbE switch blade	HP
40GbE	689638-B21	Mellanox SX1018HP Enet Switch 40G Ethernet	HP
IB DDR	410398-B21	HP BLc 4X DDR IB Switch	HP
IB FDR	775144-001	SwitchX-2 based 18-port QSFP FDR 1U unmanaged InfiniBand switch; R6; compatible to HP Apollo racks	HP
IB FDR	648311-B21	HP BLc 4X FDR IB Switch	HP
IB QDR	489184-B21	HP BLc 4X QDR IB Switch	HP
10/40Gb/s	IBM G8264	IBM 10/40GB ETH switch	IBM
10GbE	B22	IBM B22 10 Gigabit Scalable Switch Module	IBM
10GbE	EN4093	IBM PureFlex System Fabric EN4093 10 Gigabit Scalable Switch Module	IBM
40GbE	IBM G8316	IBM 40GB RackSwitch G8316	IBM
40GbE	90Y3477	BM Flex System EN6131 40Gb Ethernet Switch	IBM
IB FDR	90Y3452	IBM Flex System IB6131 Infiniband Switch	IBM
10/40Gb/s	Juniper EX3500	Juniper 10/40GB ETH switch	Juniper
10Gb/s	Juniper EX2500	Juniper 10GB ETH switch	Juniper
10Gb/s	Juniper EX4550	Juniper 10GB ETH switch	Juniper
40GbE	JuniperQFX5100	Juniper40GB ETH switch	Juniper
FDR	MSX6036F-1SFR	SwitchX based FDR InfiniBand Switch; 36 QSFP; Managed	Mellanox
FDR	SRDFSH36F-1BF	SwitchX based FDR InfiniBand Switch; 36 QSFP; Managed	Mellanox

Table 4 - Tested Switches (Sheet 3 of 4)

Speed	OPN # /Name	Description	Vendor
QDR	MIS5030Q-2SFC	InfiniScale IV IS5030 36 ports QDR InfiniBand Switch	Mellanox
10/40Gb/s	MSX1024B-1BFS	SwitchX®-2 based 48-port SFP+ 10GbE, 12 port QSFP 40GbE, 1U Ethernet switch	Mellanox
10Gb/s	MSX1016X-1BFR	SwitchX™ based 64-port SFP+ 10GigE, 1U Ethernet switch	Mellanox
40Gb/s	MSX1036B-1BFR	SwitchX™ based 36-port QSFP 40GigE 1U Ethernet	Mellanox
EDR	MSB7790-EB2F	Switch-IB(TM) based EDR InfiniBand Switch, 36 QSFP ports, non-blocking switching capacity of 7.2Tbps,	Mellanox
IB DDR	Mellanox M2401G	Infiniscale III 24-Port 20Gb/s InfiniBand Switch for Dell M1000E Blade System	Mellanox
IB DDR	F-X430044	24-port DDR-Switch	Mellanox
IB EDR	SB7700	Scorpion 7700 - Mellanox 36-port EDR 100Gb/s InfiniBand Switch	Mellanox
IB FDR	MSX6710-FB2F2	SwitchX®-2 based FDR InfiniBand 1U Switch, 36 QSFP+ ports, 2 Power Supplies (AC), x86 dual core, short depth, P2C airflow, Rail Kit, RoHS6	Mellanox
IB FDR	MSX6036F-1BFR	SwitchX™ based FDR InfiniBand Switch, 36 QSFP ports, 1 Power Supply, Short depth, Managed, PSU side to Connector side airflow, Rail Kit and RoHS6	Mellanox
IB FDR	Mellanox M4001F	SwitchX® 56Gb/s 16+16 port InfiniBand switch blade for the Dell M1000e Blade System	Mellanox
IB FDR	SX6710	Neptune 83 - Mellanox 36-port FDR 56Gb/s Infini-Band Switch	Mellanox
IB FDR10	MSX6025T-1SFR	SwitchX™ based FDR10 Infiniband Switch, 36 QSFP ports, 1 Power Supply, Standard depth, Unmanaged, PSU side to Connector side airflow, Rail Kit and RoHS6	Mellanox
IB FDR10	Mellanox M4001T	SwitchX® 40Gb/s 16+16 port InfiniBand switch blade for the Dell M1000e Blade System	Mellanox
IB QDR	MIS5025Q-1SFC	InfiniScale® IV QDR InfiniBand Switch, 36 QSFP ports, 1 Power Supply, Unmanaged, PSU side to connector side airflow, Standard depth, Rail Kit and RoHS5	Mellanox
IB QDR	MIS5024Q-1BFR	InfiniScale® IV QDR InfiniBand Switch, 36 QSFP ports, 1 power supply, Unmanaged, PSU side to Connector side airflow, no FRUs, with rack rails, Short Depth Form Factor	Mellanox

Table 4 - Tested Switches (Sheet 4 of 4)

Speed	OPN # /Name	Description	Vendor
IB QDR	QDR-Switch 4036	InfiniScale® IV QDR Mellanox Grid Director 4036 36-Port QDR ,InfiniBand Switch - Part ID: VLT- 30011	Mellanox
IB QDR	Mellanox M3601Q	40Gb/s 16+16 port InfiniBand switch blade for the Dell M1000e Blade System	Mellanox
IB SDR	F-X430060	24-port SDR-Switch	Mellanox
IB DDR	9024	24-port DDR-Switch	Qlogic
IB QDR	12300	36-Port 40Gb QDR Infiniband Switch, Management Module, Dual Power	Qlogic
1/10Gb/s	Summit X650	Extreme 10GB ETH switch	Summit

1.4 Tools, Switch Firmware and Driver Software

Firmware Rev 2.35.5100 is tested with the following tools, SwitchX® firmware, and driver software:

Table 5 - Tools, Switch Firmware and Driver Software

	Supported Version
MLNX_OFED	3.1-1.0.0/3.0-2.0.4/2.4-1.0.0
MLNX_EN (MLNX_OFED based code)	3.1-1.0.0/3.0-2.0.4/2.4-1.0.0
WinOF	4.95/4.90
VMware	1.9.9.4/1.8.2.4
MFT	4.1.0/4.0.0
SwitchX/SwitchX-2 Firmware	v9.3.2000
InfiniScale 4 Firmware	v7.4.3000

1.5 Supported FlexBoot

Firmware Rev 2.35.5100 supports the following FlexBoot version:

Table 6 - Supported FlexBoot

	Supported Version
FlexBoot	3.4.648

1.6 Revision Compatibility

Firmware Rev 2.35.5100 complies with the following programmer's reference manual:

- *ConnectX Programmer's Reference Manual (PRM), Rev 2.0 or later*, which has Command Interface Revision 0x3. The command interface revision can be retrieved by means of the `QUERY_FW` command and is indicated by the field `cmd_interface_rev`.

1.7 Firmware Burning Notes

- Firmware Family Version (FFV)

As of firmware v2.30.8000, all firmware images have the FFV field populated. The FFV value is identical to the firmware version but in a different format.

FFV format example:

```
FW version:      2.30.8000
FFV:             02.30.80.00
```

- Updating EXP_ROM

Updating only the EXP_ROM (FlexBoot) for firmware images which contain FFV requires an additional MFT flag: `"-allow_rom_change"`

The following is an example for removing the EXP_ROM from the binary image using Flint (a Mellanox device located at PCI bus function 05:00.0):

```
$ flint -d 05:00.0 -allow_rom_change drom
```

2 Firmware Rev 2.35.5100 Changes and New Features

Table 7 - Firmware Rev 2.35.5100 Changes and New Features

Category	Description
PRM: Performance	New performance and back-pressure counters command via PRM (For further information, please refer to the PRM)
PRM: Packet Steering	Support for Multicast/Unicast sniffer rules (For further information, please refer to the PRM)
PRM: QinQ	Support for VLAN in VLAN encapsulation (For further information, please refer to the PRM)
PRM: QP and CQ initialization optimizations	<ul style="list-style-type: none"> • CQ creation offload by software • Support for rst2rts command
PRM: Non-Volatile configuration	Invalidates a TLV during the firmware boot stage
PRM: Diagnostic report	A new counter for the <code>diag_rprt</code> PRM command to count packet drops due to no-receive buffer
PRM: Ethernet Head of Queue	Support for Ethernet TX lifetime cycle control (Head of Queue)
PRM: Access_Reg	A new register (PPLR) that allows egress and external loopback control (For further information, please refer to the PRM)
PRM: NIC resiliency	A watchdog mechanism to track ingress traffic stalls to prevent flooding the network with Flow Control packets
LED scheme	Inspur LED scheme: A new LED scheme controlled by the INI which causes constant traffic LED indication even without traffic.

3 Known Issues

The following table describes known issues in this firmware release and possible workarounds.

Table 8 - Known Issues

Index	Issue	Description	Workaround	Scheduled Release (fix)
1.	Downgrade to previous GA requires server reboot.	Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.	Reboot the server.	Future Release
2.	GUID ConnectX®-3 Ethernet adapter cards	On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using ibstat). Mlxburn/flint return 0xffff as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.	N/A. Please use the GUID value returned by the fabric/driver utilities (not 0xffff).	N/A
3.	SBR assertion	SBR should be asserted for a minimum of 50 milliseconds for the ConnectX-3 adapters	N/A	N/A
4.	PCIe	On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed	Production SL230 should be used for PCIe Gen3 operation	N/A
5.	Kernel panic in SR-IOV with RH6.3 Inbox driver and VPI cards	RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.	Set the "do_sense=false" parameter in the [IB_TAB] in the INI of the VPI card	N/A
6.	Side band Management compatibility with SR-IOV	In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.	N/A	Future Release
7.	SR-IOV disabled in the BIOS	When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.	Enable SR-IOV in the BIOS	Future Release

Table 8 - Known Issues

Index	Issue	Description	Workaround	Scheduled Release (fix)
8.	MFT locking of flash semaphore	MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.	Clear the semaphore using MFT command: 'flint -clear_semaphore'	Future Release
9.	MC2210411-SR4 module with Cable Info MAD	Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module	N/A	Future Release
10.	PCIe failure on temperature shock 10C/min	Gen2 failure at temperature sweep up to 10C/min (for MT27518A1-FDIR-BV only).	N/A	Future Release
11.	PCIe Gen2 link	PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1-FDIR-BV	N/A	Future Release
12.	Changing from an LLR to non-LLR requires driver restart	Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between SwitchX® and GD4036).	N/A	Future Release
13.	Bloom filter	Bloom filter is currently not supported.	N/A	Future Release
14.	Firmware downgrade	When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, the following message is displayed due to the mlxconfig tool: You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y You are trying to restore default configuration, do you want to continue ? (y/n) [n] : y	N/A	Future Release
15.	DMFS steering mode with IB in Linux	DMFS should not be enabled when working with InfiniBand on MLNX_OFED-2.0.3	Upgrade to MLNX_OFED-2.1-x.x.x or later	Future Release
16.	VPD read-only fields	VPD read-only fields are writable.	Do not write to read-only fields if you wish to preserve them	Future Release

Table 8 - Known Issues

Index	Issue	Description	Workaround	Scheduled Release (fix)
17.	Increasing SymbolErrorCounter	When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly	N/A	Future Release
18.	128 Byte CQ/EQ stride compatibility with sideband Management	Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.	N/A	Future Release
19.	128 Byte CQ/EQ stride	CQ and EQ cannot be configured to different stride sizes.	N/A	Future Release
20.	VPI port protocol change on a port with sideband Management	Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.	1. Unplug the cable from the switch 2. Restart driver 3. Change the protocol via the appropriate tools.	N/A
21.	Link Up time	Habanero (P/N MCX349A-XCCN) may experience longer linkup times of a few seconds with specific switches.	N/A	Future Release
22.	Port identification	Habanero (P/N MCX349A-XCCN) does not respond to ethtool "identify" command (ethtool -p/--identify).	N/A	Future Release
23.	RDP over IPv6	RDP over IPv6 is currently not functional.	N/A	Future Release
24.	Unicast/Multicast sniffer	Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to "push to that rule"	N/A	Future Release
25.	Boot Entry Vector (BEV)	Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.	N/A	Future Release

4 Bug Fixes History

Table 9 lists the bugs fixed in this release.

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
1.	SR-IOV security	Prevented a Virtual Function from injecting pause frames into the network.	2.30.8000	2.35.5100
1.	PRM:SET_PORT.macc_table	Fixed a wrong hash index calculation during inbound traffic.	2.33.5100	2.35.5100
2.	RDP over IPv4	Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.	2.30.8000	2.35.5100
3.	NC-SI	MLNX_OEM command GET_TEMP returned a wrong value in the max_temp field.	2.34.5000	2.35.5100
4.	MTU exceptions	Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.	2.32.5100	2.35.5100
5.	NVCONFIG failure	Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.	2.34.5000	2.35.5100
6.	IB/RoCE retransmission	Fixed a race in handling a duplicated "read request from middle".	2.34.5000	2.35.5100
7.	IB traffic issues	Fixed an issue which caused lack of IB traffic on SR-IOV VPI.	2.33.5000	2.35.5100
8.	NVRAM issues	Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.	2.34.5000	2.35.5100
9.	IB APM	Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.	2.33.5100	2.35.5100
10.	QP alternate context error	Fixed an issue which caused a firmware internal error when handling QP alternative context.	2.34.5000	2.35.5100
11.	Flow Control security issue	Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.	2.32.5100	2.35.5100
12.	Wrong temperature reporting	Wrong temperature reporting when server is in Auxiliary mode after Moonshot AC power cycle.	2.34.5000	2.35.5100

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
13.	Link down on Habanaero	Fixed a link down issue with 100MbaseT speed.	2.33.5100	2.34.5000
14.	Packet Ethertype	Fixed a mistakenly dropped ETH packet with ethertype 0x600 by the NIC.	2.30.8000	2.34.5000
15.	Broadcast traffic lost	Fixed a case preventing broadcast traffic from arriving to their destination after detaching high priority broadcast rule on a port where NC-SI was enabled.	2.33.5100	2.34.5000
16.	Low link speed	Fixed an issue where the port raised as SDR vs. InfiniScale IV QDR Switch	2.33.5100	2.34.5000
17.	40GbE Link down	Fixed a failure to read cable parameter which caused link failure on 40GbE dual port OCP devices.	2.33.5100	2.34.5000
18.	RDMA read retransmission	Fixed a rare case of completion Error with Bad Opcode sequence status which occurred when retransmitting read requests.	2.33.5100	2.34.5000
19.	VM QoS	Fixed a case where the actual bandwidth did not match the user settings in VM QoS.	2.33.5100	2.34.5000
20.	Sideband communication loss	Fixed a case where on rare cases, communication to BMC was lost during driver initialization.	2.33.5100	2.34.5000
21.	LED behavior	Fixed a wrong LED behavior when the driver is disabled in the following adapter cards: MCX346A-BCQN, MCX345A-BCQN.	2.33.5100	2.34.5000
22.	Link down on cable plugging	Fixed an issue with cable reading, which caused the link not to raise	2.33.5100	2.34.5000
23.	PRM: EQN range	Set the maximum EQN number to 1024.	2.30.8000	2.34.5000
24.	Vital Product Data read failure	Fixed a rare issue with VPD init flow which caused read failures.	2.31.5050	2.34.5000
25.	PRM: Statistic counters not reported	Fixed an issue with RX size counter not being reported.	2.30.8000	2.34.5000
26.	RoCE/InfiniBand reliable connection	The first Read response was not treated as implicit ACK.	2.30.8000	2.33.5100
27.	40GbE Link up time	Reduced a long 40GbE link up time with Cisco Nexus3064 and Arista-7050S	2.32.5100	2.33.5100

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
28.	Promiscuous mode	Fixed promiscuous mode compatibility with A0-DMFS steering.	2.32.5100	2.33.5000
29.		Fixed promiscuous mode compatibility when NC-SI is enabled and configured.	2.32.5100	2.33.5000
30.	NC-SI OEM commands	Fixed sending/receiving OEM temp commands (set/get) with channel ID 0x1f failure.	2.32.5100	2.33.5000
31.	Packet Drops	Fixed an issue which caused packets to drop on a port when changing the interface state of the other port.	2.32.5100	2.33.5000
32.	Side Band Functionality	Fixed long management communication loss and SOL hang during reboot cycles.	2.32.5100	2.33.5000
33.		Fixed wrong processing of inbound traffic towards BMC which caused communication loss.	2.32.5100	2.33.5000
34.		Fixed management link loss upon closing port interface through the driver.	2.32.5100	2.33.5000
35.	NC-SI on SFP+ Adapter Cards	Fixed a false indication in firmware of an expander presence causing delay in EEPROM reading.	2.32.5100	2.33.5000
36.	Port Links	Fixed an issue which caused a link down on a port when the cable was removed from the other port.	2.32.5100	2.33.5000
37.	Inbound Packet Processing	Fixed a rare case where packet with length zero got stuck in hardware queues.	2.32.5100	2.33.5000
38.		Fixed an issue which caused InfiniBand congestion control packet (CNP) to hang in hardware.	2.32.5100	2.33.5000
39.	Asynchronous Event Notification (AEN)	Fixed an issue which caused AEN to be sent after channel reset.	2.32.5100	2.33.5000
40.	Bandwidth Degradation with QoS	Fixed an issue which prevented the restoring of QoS setting to its default consequently causing bandwidth degradation.	2.31.5050	2.33.5000
41.	Port Link Up Time	Fixed an occasional long link up time with 10GbE based devices.	2.32.5100	2.33.5000
42.	SFP Cable Reading	Fixed an issue preventing cable readings from i2c slave address 0x51	2.32.5100	2.33.5000
43.	PCIe Gen3 Equalization	Fixed a wrong parity bit calculation when transmitting PCIe TS1 packets.	2.32.5100	2.33.5000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
44.	PCIe Power Management	Fixed a possible deadlock in PM turnoff request transmission and ack acceptance flow.	2.32.5100	2.33.5000
45.	PCIe width Degrade	Fixed a rare case with alignments state machines which caused occasional width degradation.	2.32.5100	2.33.5000
46.	Rate Limiters Hang with ECN/QCN Enabled	Fixed an issue where the transmit queues hanged while congestion control was enabled and operational (EQC/QCN)	2.32.5100	2.33.5000
47.	Unexpected Completion Syndrome with Status 0x77	Fixed an unexpected work completion syndrome with vendor syndrome 0x77 received when running RDMA SEN/WRITE traffic with retransmissions.	2.30.8000	2.33.5000
48.	IB Spec MADs	Fixed an issue which caused <code>SetPortInfo</code> to return a good status when receiving invalid <code>LinkSpeedEnabled</code> value.	2.32.5100	2.33.5000
49.	GPIO Mapping	Fixed an issue which caused dual port SFPP module cards to be automatically mapped with expander	2.32.5100	2.33.5000
50.	Steering Mode	Fixed an issue where firmware overrides the steering mode that was chosen by the driver.	2.32.5100	2.33.5000
51.	Port sensing	Fixed invalid return sensing results occurred when the link was up.	2.32.5100	2.33.5000
52.		Fixed an issue causing the sensing result to be delayed when cable was unplugged.	2.32.5100	2.33.5000
53.	Wrong link type display	Fixed an issue causing the link type to be displayed as ETH when set to AUTO.	2.32.5100	2.33.5000
54.	IBDump performance	Fixed performance degradation when running IBDump	2.30.8000	2.32.5100
55.	PCIe link Disable/Enable	Occasionally, a link training timeout occurred in EQ phase0 during disable/enable test.	2.31.5050	2.32.5100
56.	40GbE QoS	Improved strict bandwidth mode functionality	2.30.8000	2.32.5100
57.	Port Counters reporting	Fixed an issue with the <code>PortRcvPkts</code> counter always displaying zero value.	2.31.5050	2.32.5100
58.	GMP MADs in SecureHost	Fixed an issue with processing GMP MADs with SET method in SecureHost mode.	2.31.5050	2.32.5100

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
59.	NC-SI over IPv6	Fixed an issue causing a wrong usage of MCG size when configuring Global Multicast filter	2.31.5050	2.32.5100
60.	NC SI link failure	Disabling the first port occasionally causes second port TX failure.	2.31.5050	2.32.5100
61.	10GbE link failure	Fixed a mismatch in links status reported. The adapter reports links as down while the switch perceives them as up	2.31.5050	2.32.5100
62.	Link failure	Fixed an occasional 40GbE link failure with SCM5 Switch blade	2.31.5050	2.32.5100
63.	ExtPortInfo MAD	Fixed a wrong FDR10 speed reporting in MAD	2.31.5050	2.32.5100
64.	IB link failure	Fixed an issue preventing the ports to rise up when set to FDR10 vs QDR	2.31.5050	2.32.5100
65.	40GbE link failure	Fixed an occasional link failure vs Arista switch	2.31.5050	2.32.5100
66.	RDMA Write retransmission	Retransmission started from the first PSN of message instead of the last acknowledged PSN	2.30.3200	2.32.5100
67.	Firmware burning	Firmware hangs when receiving GeneralInfoMad during inline firmware burning	2.30.3200	2.32.5100
68.	PCIe PML1	L1 flow adjustments and threshold tuning	2.31.5050	2.32.5100
69.	PCIe reset	Fixed a rare hanging issue during PERST_assertion	2.31.5050	2.32.5100
70.	PCIe Gen3 EQ	Wrong coefficients were reported during phase3	2.31.5050	2.32.5100
71.	Boot	Fixed an issue causing wrong behavior due to reset timing	2.31.5050	2.32.5100
72.	SMBUS	Fixed long timeout issues	2.31.5050	2.32.5100
73.	NVRAM	Fixed NVRAM write issues in driver-less mode	2.31.5050	2.32.5100
74.	40GbE Link support	Fixed 40GbE link support in aux mode	2.31.5050	2.32.5100
75.	NC-SI	Dropped commands with non-existing channel ID	2.31.5050	2.32.5100
76.	PRM PortInfo command	Fixed issues in extended speed reporting	2.31.5050	2.32.5100
77.	Trap 257/8(IB)	Fixed bad QP reporting in trap 257/8	2.30.8000	2.32.5100

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
78.	Bad Q_KEY errors	Fixed an issue causing false bad q_key error messages	2.30.8000	2.32.5100
79.	PFC	Fixed Pause Frame opcode mismatch	2.30.8000	2.32.5100
80.	Sideband Communication	Fixed communication loss upon PCIe error detection	2.31.5050	2.32.5100
81.	NC-SI	Fixed wrong channel value in the SELECT/DESELECT PACKAGE commands	2.30.8000	2.31.5050
82.		Fixed an issue caused response packet to include 4 extra bytes	2.30.8000	2.31.5050
83.		Fixed wrong reason code value returned when using Set Link command with unsupported speed.	2.30.8000	2.31.5050
84.		Added protection from bad MAC address given by BMC	2.30.8000	2.31.5050
85.	False Link Indication	Fixed an issue causing the device to report false link up when no cable is connected.	2.30.8000	2.31.5050
86.	PCIe	Removed false TX pulse after PERST_ deassertion	2.30.8000	2.31.5050
87.		Fixed FLR capability bit inconsistency when SR-IOV is enabled.	2.30.3200	2.31.5050
88.		Fixed an issue with the device not reporting PCIe related errors.	2.30.8000	2.31.5050
89.	SDR instead of DDR ConnectX-3 to SX6036	When a link is configured to DDR in a setup of ConnectX-3 to SX6036, SDR link is established instead.	2.30.8000	2.31.5050
90.	VXLAN	VXLAN used the wrong default UDP port. the UDP port number was changed to 4789.	2.30.8000	2.31.5050
91.		Fixed wrong setting of the UDP destination port for VXLAN.	2.30.8000	2.31.5050
92.	Flow Steering	Fixed an internal error caused when moving to the DMS mode with IPMI/NC-SI enabled.	2.30.8000	2.31.5050
93.	FDR speed degradation with 0.5m cables	In a back-to-back setup of FDR cards connected with a 0.5m FDR cable, a link may be established as FDR10 instead of FDR.	2.30.3200	2.31.5050
94.	PCI interrupt	Fixed issues related to working with PCI legacy interrupts.	2.30.8000	2.31.5050

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
95.	TCP/UDP Checksum	Fixed wrong checksum calculation for short packets which were padded by the software.	2.30.8000	2.31.5050
96.	MFT tool deadlock	Reading PCIe configuration space after using the MFT flint tool caused the device to crash.	2.10.0000	2.31.5050
97.	Side band packet loss	Fixed occasional packet loss over IPMI	2.30.8000	2.31.5050
98.	Eye opening MAD	Fixed wrong values reported in the Eye opening MAD.	2.30.8000	2.31.5050
99.	PCIe Link width	Fixed occasional link width degrades during link negotiation and link transitions from L1 state.	2.30.8000	2.31.5050
100.	PCIe signal detect	Fixed adjust signal detect thresholds	2.30.8000	2.31.5050
101.	Error counters	PortExtendedSpeedsCounters MAD counters were mistakenly increased while LLR was active	2.30.8000	2.31.5050
102.	PCIe Gen3 Equalization	Lane reversal was not considered when configured TX parameters	2.30.8000	2.31.5050
103.	Reset On LAN (ROL)	Fixed ROL factory MAC usage when a FlexBoot address was given.	2.30.8000	2.31.5050
104.	Flow Control	Fixed Pause frames factory MAC usage when a FlexBoot address was given.	2.30.3200	2.31.5050
105.	WOL/ROL	The device did not different between WOL/ROL packets.	2.30.8000	2.31.5050
106.	PortInfo MAD	Fixed a set of extended fields in PortInfo MAD which did not function.	2.10.0000	2.31.5050
107.	LLR cell size	Adjusted LLR cell size according to the MLPN negotiation of ib_128b_llr	2.30.8000	2.31.5050
108.	Link max speed	The max speed restriction was active in full power mode instead of standby mode only.	2.30.8000	2.31.5050
109.	InfiniBand Automatic Path Migration	The InfiniBand Path migration did not work with GRH. http://webdev01:8080/commit/ConnectX.git/a9c37ee4c31038f2c1179d4d9e79c9337e0ab5c7	2.10.0000	2.31.5050
110.	Packet steering	Reading MGM after writing it returned wrong members count.	2.30.8000	2.31.5050

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
111.	RSS QP context	Fixed corruption of the RSS hash key given by the driver.	2.30.8000	2.31.5050
112.	10Gb/s QoS	Fixed QoS rate limit bandwidth offset.	2.30.3200	2.31.5050
113.	ExtendedPortInfo MAD	Fixed FDR10 speed_en reporting.	2.30.8000	2.31.5050
114.	Management link	Fixed long management link com loss.	2.30.8000	2.31.5050
115.	PRM Query_Port Command	The command results reported both link types active at the same time.	2.30.3200	2.31.5050
116.	Link not raising	Fixed collision between forcing phy type and port sensing.	2.30.8000	2.31.5050
117.	Core clock reporting	Fixed a wrong core clock freq reporting in QUERY_HCA command.	2.30.3200	2.31.5050
118.	56GbE link issues	Fixeds occasional link failure when 56GbE is enabled	2.30.8000	2.31.5050
119.	RX calibration	Fixed max eye margins to be per protocol.	2.30.8000	2.31.5050
120.	VPI symbol errors	perfquery reported wrong error symbol on ConnectX [®] -3 VPI mode: IB, ETH.	2.30.8000	2.31.5050
121.	Symbol error on ConnectX-3 dual-port QDR with MC2207312-030 AOCs	On ConnectX-3 dual-port QDR and FDR/FDR10 switch setups, symbol errors may occur with MC2207312-030 AOCs.	2.30.8000	2.31.5050
122.	Symbol error on Falcon QDR against FDR switches with MC2207126-004 copper cables	Symbol errors occur on ConnectX-3 dual-port QDR connected to FDR switches with MC2207126-004 copper cables.	2.30.8000	2.31.5050
123.	PCIe correctable errors in speed change	When PCIe Gen3 is enabled, temporary correctable errors might occur when changing speed between PCIe Gen1 and PCIe Gen2.	2.10.0000	2.30.8000
124.	Incompatibility between Device managed Flow steering and NC-SI	Device managed Flow steering and NC-SI cannot be enabled simultaneously.	2.11.0500	2.30.8000
125.	40GbE is not supported in Auto-Sensing	Auto-Sensing is not supported with 40GbE connections in VPI cards	2.10.0000	2.30.8000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
126.	InfiniBand port_rcv_pkts counter	InfiniBand port_rcv_pkts counter over counts when LLR is enabled on the port. The port_rcv_pkts counter continues to count packets even when no traffic is received.	2.10.0000	2.30.8000
127.	PXE	PXE is currently not supported in 40GbE in VPI cards	2.10.0000	2.30.8000
128.		PXE is currently not supported in QSFP to SFP+ hybrid cable	2.10.0000	2.30.8000
129.	sense_port failure	Ethernet cards failed to work with MLNX_OFED unless the do_sense was disabled in the INI	RH6.4 driver	MLNX_OFED 2.0-3.0.0
130.	Link errors	BER of 10^{-11} with 7M copper SFP+ 10GbE cable against Arista switch	2.30.3200	2.30.8000
131.	Linkup Failure vs SwitchX®-2 based switch	Port failed to link up in 10GbE if it was previously linked up in 40GbE vs. SwitchX®-2 based switch	2.30.3200	2.30.8000
132.	NC-SI 40GbE reporting	Added 40GbE reporting in get_link_status NC-SI command	2.30.3000	2.30.8000
133.	Packets drop in receive when DMFS enabled	Steering entries overlapping caused packets to drop in the receive due to wrong hash size calculation of QP hash folding.	2.30.3000	2.30.8000
134.	PCIe speed degrade	Occasionally, PCIe speed degraded during speed change test	2.30.3000	2.30.8000
135.	Link failure vs Cisco	Device failed to raise the link against Cisco b-22 Blade switch	2.30.3000	2.30.8000
136.	False RX drops indication	Fixed an issue causing RX drop counters to falsely increase when using MLNX_OFED 2.0.-3.0.0	2.30.3000	2.30.8000
137.	NC-SI wrong command info	Wrong port information provided in get link status command.	2.30.3000	2.30.8000
138.	Port interfaces stay down	After firmware upgrade, the device failed to raise port interface.	2.30.3000	2.30.8000
139.	SR-IOV guest failure	Guest VM failed to execute firmware commands operations and crashed.	2.30.3000	2.30.8000
140.	ConnectX®-3 Pro: MCG write timeout	PRM WRITE_MCG command caused the device to hang.	2.30.3000	2.30.8000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
141.	ConnectX®-3 Pro: Driver start failure	Driver could not start when NIC was configured for NC-SI SNP.	2.30.3000	2.30.8000
142.	SR-IOV command timeouts	Guest MSIX vectors were not assigned properly.	2.30.3000	2.30.8000
143.	PCIe speed degrade/link down	Occasionally, the PCIe link experienced speed degrading or link falling in driver restart/reboot	2.30.3000	2.30.8000
144.	QP Sniffer issue	Fixed a hash fold issue for sniffer QPs	2.30.3000	2.30.8000
145.	Long link up time	A long link up time is experienced in the HCA connected to a 10GbE cable against the MSX1012 switch	2.30.3000	2.30.8000
146.	PCIe TS parity bit	In recovery.EQLZ state TSs used incorrect parity bit calculation	2.30.3000	2.30.8000
147.	PRM Init_port failure	Init port command may fail on a system with NC-SI	2.30.3000	2.30.8000
148.	PortInfo MAD link width support	Wrong link_width_support is reported occasionally in PORT_INFO MAD	2.30.3000	2.30.8000
149.	Wrong Virtual Function completer ID	In SR-IOV a wrong completer ID is added in some of the VF completion packets	2.30.3000	2.30.8000
150.	PCIe PML1 failures	Fixed occasional failures upon entering and exiting L1 state in PCIe Gen1 & 2 speeds	2.30.3000	2.30.8000
151.	IB: APM failures in ConnectX-3 Pro	Occasional FSM transition timeouts are seen on APM requests	2.30.3000	2.30.8000
152.	ipmitool OOB commands	On rare occasions, ipmitool OOB commands failed upon send payload.	2.30.3000	2.30.8000
153.	Sideband communication	On rare occasions, after stress of power cycles, side-band communication might disconnect.	2.30.3000	2.30.8000
154.	Expansion ROM partition	Expansion ROM partition not found	2.30.3000	2.30.8000
155.	AC power cycle issue	In certain servers, AC power cycle may cause BMC connectivity loss.	2.30.3000	2.30.8000
156.	PXE issue	Occasionally, during DC cycle stress, failure occurred in PXE due to race condition	2.30.3000	2.30.8000
157.	SMBUS communication	SMBUS communication lost during AC/DC cycle	2.30.3000	2.30.8000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
158.	MTU configuration	Temporal wrong MTU configuration during initialization may cause Serial over LAN disconnection	2.30.3000	2.30.8000
159.	IPMI connectivity	IPMI OOB communication lost during stress	2.30.3000	2.30.8000
160.	iperf stress test	Packet drops during iperf stress w/ different MSS	2.30.3000	2.30.8000
161.	Loss of connection to BMC upon firmware upgrade	Upgrading from firmware v2.10.3898 may cause loss of connection to BMC.	2.30.3000	2.30.8000
162.	Running rmmmod may cause unexpected behavior	Removing the mlx4_en driver using the "rmmmod" command, may cause unexpected behavior	2.30.3000	2.30.8000
163.	IPMI connectivity	On rare occasions, after stress of BMC cold reset, link failure might occur	2.30.3000	2.30.8000
164.	Flexboot 3.4.100-UEFI-4.0.410 BIOS menu	Enter the BIOS menu while using Flex-Boot 3.4.100- UEFI-4.0.410 may cause the server to stop responding (hang)	2.30.3000	2.30.8000
165.	ROL failure	ROL failure after disassembling the driver on the SUT	2.30.3000	2.30.8000
166.	IPMI link failure	IPMI link failure after disabling the WoL or disassembling the driver	2.30.3000	2.30.8000
167.	WoL and RoL issues	WoL and RoL issues caused when the IPMI is disabled	2.30.3000	2.30.8000
168.	A link flapping issue	Alignment marker arrival can no longer drop the link.	2.30.3000	2.30.8000
169.	IPMI - SOL traffic performance improvement	SOL with multiple data streams occasionally hang	2.30.3000	2.30.8000
170.	RoCE	RoCE does not function properly after running "ethtool ethX"	2.30.3000	2.30.8000
171.	PCI link errors	PCI link errors false indication. Cleared errors during PCIe link retraining	2.30.3000	2.30.8000
172.	PCIe speed change	Fixed a false indication for incoming PCIe speed change request	2.30.3000	2.30.8000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
173.	No NC-SI after PXE teardown	Management transport was not supported, after PXE driver teardown (unload). Fixed the flow to issue software reset, after the driver was stopped	2.30.3000	2.30.8000
174.	Ports PLL calibration issue	PLL calibration were affected by operating point configuration	2.30.3000	2.30.8000
175.	Cable Info MAD issue	Wrong cable info was received when using the MC2210411-SR4 module	2.30.3000	2.30.8000
176.	Revision ID	Updated the Revision ID of Node Info and General Info MADs to reflect HW Rev ID instead of 0	2.30.3000	2.30.8000
177.	Port Error counters reset	Port error counters were not cleared upon XAUI/SGMII link up	2.30.3000	2.30.8000
178.	RDMA retransmission on ConnectX®-3 Pro	RDMA retransmission failed in specific scenario of receiving NAKs on ConnectX®-3 Pro due to bad static configuration	2.30.3000	2.30.8000
179.	NMI on PCIe Gen2 server	Fixed a PCIe Gen2 firmware flow to prevent NMI during hibernation on PCIe Gen2 server	2.30.3000	2.30.8000
180.	Access to closed resources	Fixed a possible access to unmapped resource memory	2.30.3000	2.30.8000
181.	Slow link establishment in NC-SI	Slow link establishment in NC-SI caused due to slow cable reading in boot	2.30.3000	2.30.8000
182.	PCIe speed change	Occasionally, a failure occurred in speed when changing to Gen2	2.30.3000	2.30.8000
183.	PXE teardown issue	PXE might halt during teardown	2.30.3000	2.30.8000
184.	InfiniBand loopback	InfiniBand loopback was blocked during link negotiation on the same port	2.11.0500	2.30.8000
185.	Voltage scaling	Fixed process voltage scaling issue	2.30.3000	2.30.8000
186.	DMA address 0x0	Fixed a possible read access to DMA address 0x0	2.11.0500	2.30.8000
187.	cqe issue	Fixed miss cqe issue due to interrupt moderation	2.11.0500	2.30.8000
188.	Cable reading issue	Fixed a rare cable reading issue upon cable insertion	2.30.3000	2.30.8000
189.	Linkup issue	Fixed a linkup issue against MSX60XX FDR switch	2.30.3000	2.30.8000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
190.	LLR Vendor Specific MAD	LLR Dropped cell counter reported CSN error	2.11.0500	2.30.8000
191.	PXE boot failure	On rare occasions, PXE boot fails due to a firmware issue interfering with the PXE load from the card's flash. Upon failure, the following message is received: "Payload inaccessible - cannot continue"	2.30.3000	2.30.8000
192.	MLNX_OFED v2.0-2.0.3 reports ETH RX errors	MLNX_OFED v2.0-2.0.3 reported RX errors when the driver operated in the ETH only mode.	MLNX-OFED v2.0.2.0.3	2.30.3200
193.	SR-IOV guest communication channel error	Under certain conditions, SR-IOV guest experienced request timeouts and got stuck.	2.11.0500	2.30.3200
194.	No NC-SI after PXE teardown	Management transport was not supported, after PXE driver teardown (unload). Fixed the flow to issue software reset, after the driver was stopped.	2.11.0500	2.30.3000
195.	Revision ID	Updated the Revision ID of Node Info and General Info MADs to reflect hardware Rev ID instead of 0	2.11.0500	2.30.3000
196.	Ports PLL calibration issue	PLL calibration were affected by operating point configuration	2.11.0500	2.30.3000
197.	Port Error counters reset	Port error counters were not cleared upon XAUI/SGMII link up	2.11.0500	2.30.3000
198.	Receiver SerDes tuning	Enhanced the receiver SerDes tuning for 10GE, to support specific 10GbE QSFP to SFP+ splitter cables	2.11.0500	2.30.3000
199.	Access to closed resources	Fixed a possible access to unmapped resource memory	2.11.0500	2.30.3000
200.	Slow link establishment in NC-SI	Slow link establishment in NC-SI caused due to slow cable reading in boot	2.11.0500	2.30.3000
201.	PCIe speed change	Occasionally, a failure occurred in speed when changing to Gen2	2.11.0500	2.30.3000
202.	PXE teardown issue	PXE might halt during teardown	2.11.0500	2.30.3000
203.	InfiniBand loopback	InfiniBand loopback was blocked during link negotiation on the same port	2.11.0500	2.30.3000
204.	Voltage scaling	Fixed process voltage scaling issue	2.11.0500	2.30.3000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
205.	DMA address 0x0	Fixed a possible read access to DMA address 0x0	2.11.0500	2.30.3000
206.	cqe issue	Fixed miss cqe issue due to interrupt moderation	2.11.0500	2.30.3000
207.	Cable reading issue	Fixed a rare cable reading issue upon cable insertion	2.11.0500	2.30.3000
208.	PXE boot failure	On rare occasions, PXE boot fails due to a firmware issue interfering with the PXE load from the card's flash. Upon failure, the following message is received: "Payload inaccessible - cannot continue"	2.11.0500	2.30.3000
209.	Momentarily packet drop on one port while the other port goes down	When the same VLAN is configured for both ports and one port goes down, the second port may suffer a momentarily packet drop	2.11.0500	2.30.3000
210.	Advanced Error Reporting	Fixes to Advanced Error Reporting according to the PTC (PCIe compliancy) Test failures	2.11.0500	2.30.3000
211.	10GbE link remains down after changing to a 40GbE link	When changing link connection between 40Gbe to 10Gbe, the port might stay down until the next driver restart.	2.11.0500	2.30.3000
212.	Race in PCIe L1 flow	The device may enter an L1 power state before completing an incoming configuration request if it arrived before the power state change ack for Root Complex	2.11.0500	2.30.3000
213.	Wrong link speed after several cable reinsertions	During repeated cable reinsertion, the link may raise in a lower speed than expected/	2.11.0500	2.30.3000
214.	Changing port protocol from ETH to IB requires driver restart	Bad configuration of <code>ib_protocol</code> when setting the port to InfiniBand after exchanging it from Ethernet/RoCE on the same port	2.11.0500	2.30.3000
215.	Rare NMI error on HP servers when using PXE	On rare occasions, an NMI error is received when stopping PXE boot in the middle of an action on HP servers	2.11.0500	2.30.3000
216.	Race in PCI configuration handling	The system was unresponsive when a race between PCI configuration cycles handling in hardware and firmware occurred.	2.11.0500	2.30.3000
217.	RoCE breaks IPv6 traffic	IPv6 packets dropped while RoCE was enabled	2.11.0500	2.30.3000

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
218.	Link reset, HCA to SwitchX®	On rare link reset occasions, an HCA to SwitchX® link may remain in ARM state after SwitchX reboot, and not reach the Active state.	2.11.0500	2.30.3000
219.	40GbE switches link down upon repeated insertion and removing of cables	When repeatedly plugging out and plugging in cables to/from a 40GbE switch, the link remains down.	2.10.0800	2.11.0500
220.	FDR/QDR vs DDR switch	The link is raised as SDR rather than DDR	2.10.0800	2.11.0500
221.	0.5M, 1M Copper FDR cable support	0.5M, 1M Copper FDR cables (Paralink11, Paralink14) are not supported in back to back connection.	2.10.0800	2.11.0500
222.	Changing FDR cables from Fiber to Copper	Changing FDR cables from Fiber to Copper and vice versa might cause link speed degradation from FDR to FDR10 or FDR10 to QDR.	2.10.0800	2.11.0500
223.	Changing 40GbE connection	Changing 40GbE connection from back to back to a switch port and vice versa might cause the link to stay down in the ConnectX®-3 side.	2.10.0800	2.11.0500
224.	SDR vs QDR switch	InfiniBand link vs QDR switch rises as DDR or SDR	2.10.0800	2.11.0500
225.	QDR link up time	On rare occasions, the QDR link up time between an FDR card and a QDR device was up to 4 minutes	2.10.0800	2.11.0500
226.	QDR Link stability	QDR Link stability between ConnectX®-3 and InfiniScale® IV	2.10.0800	2.11.0500
227.	Signal integrity issues	Signal integrity issues in all speeds	2.10.0800	2.11.0500
228.	PCI correctable error	Fixed bad PCI reporting	2.10.0800	2.11.0500
229.	RoCE re-transmission	Not re-transmitting from the beginning of the message but from PSN NAK.	2.10.0800	2.11.0500
230.	RoCE	R-RoCE ignored SMAC check	2.10.0800	2.11.0500
231.	Function Level Reset (FLR)	FLR to PPF in SRIOV	2.10.0800	2.11.0500
232.		FLR in no-driver mode	2.10.0800	2.11.0500
233.	SR-IOV	Comchannel bug fix	2.10.0800	2.11.0500

Table 9 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
234.	40GbE performance	40GbE full wire speed was not reached with former cards configuration for MCX314 and MCX313 40GbE cards. Fix: Increased core frequency to support 40GbE full wire speed. This change requires 1V input. Affected cards: MCX313A-BCB, MCX-314A-BCB	2.10.0700	2.10.0800
235.		The ConnectX® card was not receiving frames with minimum IPG when configured to 40GbE. Fix: Updated firmware configuration. Affected cards: All cards capable of 40GbE speed	2.10.0700	2.10.0800
236.	GUIDs for RoCE	Ethernet only cards did not have GUIDs flashed on the device. This caused RoCE to fail once two or more cards were active on the same machine. Fix: The firmware generates the GUIDs from the flashed MACs for ETH only cards. Affected cards: All ETH only cards.	2.10.0700	2.10.0800
237.	40GbE signal integrity	Signal integrity improved in 40GbE speed.	2.10.0000	2.10.0700
238.				
239.	PCIe Gen3 receiver sensitivity due to BIOS changes	Due to BIOS changes required by latest Intel guidelines for PCIe Gen3, a sensitivity in PCIe eye_centering algorithm caused link degradation on some platforms.	2.10.0600	2.10.0620
240.	FDR, FDR10, 10GbE XFI/SFI signal integrity	Signal integrity improved for the following speeds: FDR, FDR10, 10GbE XFI/SFI.	2.10.0000	2.10.0600
241.				
242.	VDD_MODE GPIO changed after reset	In boards with VDD_MODE GPIO, the GPIO was dropped after reset hence, causing voltage to be reduced to 0.9v. Fix: The GPIO in boards with VDD_MODE GPIO is no longer dropped across resets.	2.10.0000	2.10.0600
243.	PCIe configuration type1 requests were dropped after a PCIe hot reset	After a PCIe hot reset, PCIe configuration type1 requests were dropped instead of being replied as unsupported. Fix: A proper notification is sent every time PCIe configuration type1 requests are dropped.	2.10.0000	2.10.0600

5 Firmware Changes and New Feature History

Table 10 - Firmware Changes and New Feature History

Firmware Version	Description
2.34.5000	<ul style="list-style-type: none"> • Added support for multiple RoCE modes (RoCE v1+v2) on the same port: RoCE mode is per connection now. • Added a new QP command "INIT2RTS_QP" to enhance QP connection readiness time. • Disabled FCS checks to support switches that replace FCS with Timestamp. • Added RX Port identification for direct rout packets. • Improved RDMA WRITE/SEND performance with retransmissions. • Enabled firmware burning/querying using the PRM ACCESS_REG command. • Added support for VAM. • Enabled bad cable EEPROM reporting to the driver. • Added support for Platform Level Data Model (PLDM) sideband protocol. • Added support for priority based A0-DMFS mode (For further information, please refer to the PRM). • Added support for Unicast/Multicast loopback disablement by the driver. (For further information, please refer to the PRM) • Removed the source IP from the hash calculation (For further information, please refer to the PRM) • Added support for Inline Receive mode up to 2KB.
2.33.5100	<ul style="list-style-type: none"> • Bug fixes - see "Bug Fixes History" on page 24
2.33.5000	<ul style="list-style-type: none"> • Bandwidth allocation support: Including maximum bandwidth and bandwidth share guarantee between VMs for InfiniBand and Ethernet. • Increased inbound traffic buffer capacity when the PFC on all priorities is enabled. • Added support for changing UAR BAR (PCI BAR 2) size. • Added support for cable sub-power class for Mellanox MFA1A00-EXXX and SMFA1A00-CXXX EDR cables. • Improvements in attachment/detachment flows' rules in both A0-DMFS and DMFS modes. • Added physical port forcing on specific QPs when virtual mapping is applied • Added support for dynamic enablement of LAG mode • Added support for vendor specific command to report the ports' MAC addresses. • Enabled 100Mb ability exposure and its enablement via an INI parameter. • Added support for SFP+ with 1GbE when the adapter card is enabled in the EEPROM. • Optimized the SideBand connectivity loss during driver initialization to minimum. • Added support for SMBUS ARP. • Enabled thermal reporting of TMP421 sensor in OCP cards. • RDMA Read retransmission optimizations to improve performance and ensure forward progress while packet drops occur. • Improved data path WQE prefetch algorithm.

Table 10 - Firmware Changes and New Feature History

Firmware Version	Description
2.32.5100	<ul style="list-style-type: none"> • Added support to query PTYS, PTOS registers through ACCESS_REG PRM command. • Added support for CLP access to NVRAM • Added support for more than 22 QPs per MCG in DMFS. • Added support for high rate steering mode (a.k.a Simplified Steering) • Added support for reading current hardware mode through the QUERY_PORT PRM command • Added CSUM mode reporting in QUERY_DEV_CAP command • Added additional configuration options for UPDATE_QP command • Added support for 128 Byte stride for CQ/EQ • Enabled module EEPROM access using command I/F • Reset Flow improvements and graceful handling of error caused by Virtual Functions • RX performance optimization for single port cards • Promiscuous mode performance improvements • Added support for Secure Host mode • Added Port protocol configuration option. • Added support for GPIO swap • 40GbE SI improvements • Added support for Temp Sensing Vendor specific MAD. • Added Temp Sensing NC-SI cmd. • Added support for AEN. • Added new command to report firmware revision. • Added support for QCN • Enabled the driver to use VXLAN offloads on TX side without Device Managed Flow Steering (DMFS) • Enabled non Mellanox cables to rise FDR10 link via new INI parameter. To unlock the cables run: <code>Fdr10_cable_stamping_override</code>
2.31.5050	<ul style="list-style-type: none"> • Added support for GeneralInfo SMP MAD • Updated capability mask in GeneralInfo SMP/GMP MAD • Added support for PortCountersVL MAD • Added support for PortSamplesControl/PortSamplesResults/PortSamplesExtended MADs • Added Exponential Backoff Timer support. It is enabled via the <code>rtm_ini</code> parameter. The default value is 0 • Added VLAN steering to Device Managed Flow Steering (DMFS) • Added support for Non-Volatile configuration of TLVs to set device attributes: <ul style="list-style-type: none"> • Query and set of configurations is available through PRM ACCESS_REG command • PRM ACCESS_REG command is now also supported through the <code>tools_hcr</code> command interface • Added support for MTF mlxconfig tool • Added IPv6 support for NC-SI and IPMI Pass-Through • Added support for the same unicast MAC simultaneously for both IPMI and NC-SI • PCIe power optimizations for 8X/4X links • SMBUS optimizations

Table 10 - Firmware Changes and New Feature History

Firmware Version	Description
2.31.5050 (cont.)	<ul style="list-style-type: none"> • Added enhancements for receiver equalization in Gen3: <ul style="list-style-type: none"> • Enhancements are enabled by the INI. The default value is disabled. Please contact Mellanox support if required to enable it. • Added new Physical and Virtual Functions reset flows support • Added support for 64Bit BIOS mode • Added IEEE802.3 CL73 autoneg support to the QUERY_PORT command. • Added factory MAC address reporting to the Query_Port command. • Added support for reverting virtual MAC configuration per port and restoring to factory MAC through MOD_STAT_CFG command. • Added support for inline TLV read through MOD_STAT_CFG command. • Added current MTU reporting to the QUERY_PORT command. • Added support query for additional MAC addresses per port (up to 7) through the QUERY_PORT command.
2.30.8000	<ul style="list-style-type: none"> • Initial GA release of ConnectX-3 Pro • UDP packets with zero checksum • RoCE v2 support, including CONFIG_DEV command support • Enabled SR-IOV by default on all Mellanox ConnectX-3 Pro cards with 8 virtual functions • indiscard packets counter support in DUMP_ETH_STAT command • NVGRE support • VXLAN support • DMFS and GRE steering: Rule insertion adjustments • Removed DIF support from reported capabilities in QUERY_DEV_CAP PRM command • Flow control by DSCP priority for IPv4 • DMFS improvements: Insertion scheme enforcement and block loopback for InfiniBand • Added I2C resiliency support • Support for NC-SI over MCTP over SMBus • Added a flash access interface for persistent (non-volatile) configuration support • Added port BW arbitration configuration through the CONFIG_DEV command • Added IP-in-IP TCP checksum offload support • PCI Express compliancy Tx and Rx adjustments • Removed software limitations that were required for the use of Mellanox-certified FDR InfiniBand cables with Mellanox FDR InfiniBand adapters and switches. Please refer to "Memo: FDR 56Gb/s InfiniBand Cables" that was released on Dec/2013. <p>Mellanox will offer an EXTENDED diagnostics support plan which will be available for mixed environments only and that will help identify issues they may encounter with the FDR installations.</p>
2.30.3200	<ul style="list-style-type: none"> • Added support for FDR AOC MC2207312-XXX • Bug Fixes, see “Bug Fixes History” on page 24

Table 10 - Firmware Changes and New Feature History

Firmware Version	Description
2.30.3000	<ul style="list-style-type: none"> • Added support for the UPDATE_QP PRM command • Added support for resetting the modified MAC addresses in the standby mode by the MOD_STAT_CFG command • Added support for receiving TCP and UDP truncated packets of certain type • Added support for 56GbE in all devices supporting 40GbE <ul style="list-style-type: none"> • Establishing 56GbE link with SwitchX® requires 56GbE enablement on the switch • Establishing 56GbE link on back to back setup requires additions to the INI. • For further information, please contact Mellanox Support • mlxconfig tool in not supported in this release • RDMA/RoCE read retransmission improvement • PFC thresholds improvements • PCI speed_change flow improvement • Added support for DIAG_RPRT per port • Added PCIe Polling Compliance mode • RoCE default configuration fixes: <ul style="list-style-type: none"> • ethertype now updated per port at SET_PORT • The default value of rroce.ip_next_protocol is 0xfe • Increased the number of extended interface counters (max_if_cnt_extended) to 0x80, as reported in QUERY_DEV_CAP PRM command • Improved link parallel detection calibration of 40GbE • Added support for PFC counters in DUMP_ETH_STAT PRM command • Fixed wrong reporting of RSS context in QUERY_FW of RSS QP • Added Sniffer QP support on Port#1 • Device managed Flow Steering performance enhancements • Disabled "pkt.dmac==qp.mac" for RoCE/RoCE over IP • Added missing loopback blocking for device managed Flow Steering • Fixed SET_PORT.mac_table configuration issue which caused minor packet loss on Port A when working in bonding mode and closing Port B. • Fixed issues with NC-SI commands reason codes • Fixed the insertion of L4 head rule in device managed Flow Steering • Added to the INI for 10/40GbE parallel detect Serdes parameters • Added support for "reset upon parity error" • Added support for 40Gb/s MC2210411-SR4 optical module • Fixed interoperability issue with the Intel 12300 switch using firmware version 6.1.0.1.11 • Improved QDR link stability when connected to InfiniScale® IV and SwitchX® switches

Table 10 - Firmware Changes and New Feature History

Firmware Version	Description
2.11.0500	<ul style="list-style-type: none"> • Added SR-IOV support • Added VPI auto-sensing support • Mellanox Link Property Negotiation (MLPN) • Enables ports to negotiate link properties between Mellanox devices. • The MLPN is activated by INI. • CR4 + KR4 • Auto-negotiation 40GBASE CR4 and KR4 as described in IEEE 802.3. • CR4 + KR4 is enabled by the INI. • 1GbE Clause37 • Auto-negotiation 1000BASE-X as described in IEEE 802.3 clause 37. • 1GbE Clause37 is enabled by default. • cable_info MAD extension for more I2C addressed • Enables different address for cable access through I2C. • cable_info MAD extension is enabled by the INI. • secure_host • smp firewall described in the PRM • Activated by the INI (active by default). • cq_2_eq mapping command • Modifies EQ by MODIFY_CQ command, described in the PRM • multi-function reserved lkey • Described in the PRM. • increase CQE timestamp to 48bit • Described in the PRM. • 56Gb Ethernet (proprietary) - Beta level • Activated by the INI (disabled by default). • mlxconfig - Beta level (requires MFT 3.0.0-3 or above) • Modifies the device cfg • FMR for SRIOV - Beta level • Described in the PRM. • Power reduction in PCI Gen3 • Fixed general_info MAD • “Bug Fixes History” on page 24
2.10.0800	<ul style="list-style-type: none"> • Bug fixes - see “Bug Fixes History” on page 24
2.10.0700	<ul style="list-style-type: none"> • Bug fixes - see “Bug Fixes History” on page 24
2.10.0000	<ul style="list-style-type: none"> • InfiniBand: <ul style="list-style-type: none"> • FDR • FDR10 • QDR • SDR • DDR • Ethernet: <ul style="list-style-type: none"> • 1GigE • 10GigE XAUI • 10GigE XFI/SFI • 40GigE • PCI Express 3.0, with backwards compatibility with v2.0 and v1.1 • Huge pages • ConnectX®-3 firmware includes all ConnectX®-2 cards supported features

6 Flexboot Changes and New Features

For further information, please refer to FlexBoot Release Notes (www.mellanox.com > Software > InfiniBand/VPI Drivers > FlexBoot).

Table 11 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.648	<ul style="list-style-type: none"> • Added support for .mrom images larger than 128kB • Added boot over IB with non-default PKey for ConnectX®-3, ConnectX®-3 Pro cards • Added support for ConnectX-4 and ConnectX-4 Lx • Synced the source with iPXE (upstream sync) • Moved to flat real mode when calling INT 1a,b101 to avoid BIOSes issues • Fixed chainloading undionly.kpxe over Connect-IB functionality • Fixed HTTP boot over IPoIB
Rev 3.4.521	<ul style="list-style-type: none"> • Added iSCSI CHAP and mutual CHAP configuration • Added the GRH size when allocating receive buffer for IPoIB • Updated VLAN netdevice's settings with all the trunk's iSCSI required settings • Updated the port event handling process • Enabled console output in Debug mode • Disabled the serial output • Disabled the banner in BEV execution • Disabled function 0x04 (in int21) when serial console is disabled • Preserved COM port settings • Fixed HTTP download over IPoIB • Fixed completion with error handling process

Table 11 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.460	<ul style="list-style-type: none"> • Boot Menu support: Added new FlexBoot GUI. The device can now be configured in the POST stage. • Non volatile memory read/write support • Configurable URI boot retry and delay between retries • Configurable iSCSI settings using DHCP/NVM • Added new interface in order to update the registered devices on the PXE stage • Enabled ConnectX Ethernet adapter cards family to work with interrupts • Enabled PXE to work in promiscuous VLAN mode (configurable through the INI) • Synced version with ipxe.org: Now the latest code in iPXE is used • Added boot priority capability: iSCSI vs PXE and fallback incase one fails • Updated the Proxy DHCP request method for non-existing option 54. ProxyDHCP request is sent to port 67 with broadcast IP address if the server identifier in option 54 is zero. Packets with source port different than BOOTPS_PORT and PXE_PORT are filtered by the PROXY • SHELL CLI is currently supported on ConnectX-3 and ConnectX-3 Pro adapter cards only • The server's IP address in DHCP server replies is now checked before checking the reply type. This will ignore NACK replies from servers which already were ignored by the client. In case of 2 DHCP servers in the same subnet, the client will eventually choose one of them, by sending the DHCP REQUEST with 'DHCP Server Identifier' (option 54) filled with the requested server's IP address. • Both the GUID and the MAC are printed on the screen when the port link layer is set as InfiniBand • PROXYDHCP and PXEBS settings are saved under netdevice settings • rootpath/filename/nextserver are now fetched from the netdevice settings • The cached DHCP packet are received only if working with the same net device. When pxelinux.0 receives the cached DHCP packet from the UNDI API, it constructs a new (fake) packet for the current net device. If the process is stopped and then restarted and booted from the next boot device which serves as the second port in the HCA, a new (fake) DHCP packet is not constructed. The previous packet which includes all the information of the first port (IP, MAC, Netmask, etc...) is used. If an old (fake) DHCP packet is discovered, its chaddr is compared to the chaddr in the pxe_netdev, if not similar, a new (fake) DHCP packet is created. • PXE shutdown is called if int22 with function 0x000C is called. • Changed DHCP discover timeouts to comply with PXE spec

Table 11 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.306	<ul style="list-style-type: none"> • Added validation script for the released ROMs • Added the option to always keep SAN hook to enable WIN install on iSCSI target • Added compilation flag around the flash readout. • Added URI Boot retry. Default retries = 0. • Added Unmap MPT command in teardown. • Added support for HII iSCSI configuration. • Added 64-bit PCI BAR support (Large bar). • Added the option added for running PXE with promiscuous VLAN. • Re-added COMBOOT image support by default. • Enabled pages-function handling in Connect-IB initialization stage to work according to the PRM. • Applied additional patches from ipxe.org • Updated the window even if ACK does not acknowledge new data. • Modified the error print to debug print. • Modified the printed string when initializing devices. • Modified the error print. Added additional information to make the output more user-friendly. • Changed the size of the domain name array to 0xfd. • Disabled the waiting period for link up on trunk-net-device when VLAN is enabled on port. • Removed unsupported EQ event in Connect-IB® • Fixed an issue for TLV with length 0. • Fixed an issue related to sync VLAN IRQ operation with trunk IRQ operation. • Fixed an issue which enabled a netdevice (VLAN) to open/close twice. • Fixed an issue which prevented the iSCSI initiator's name from being received from HII. • Fixed an issue related to dual port adapters; occasionally, booting from the second port resulted in TFTP download failure when the first port was already linked up with DHCP, and has received a TFTP address. • Fixed an issue which caused PXE boot failure when using a filename if iSCSI rootpath is set. • Fixed an issue which prevented the device to PXE boot from the 2nd port if first port was already downloaded. • Fixed compilation issue. • Fixed a broken VLAN issue. • Fixed a retry issue when the value is infinite.

Table 11 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.225	<ul style="list-style-type: none"> • Added additional information to the error print output • Added compilation flag around the flash readout • Added URI Boot retry. Default retries = 0 • Added Unmap MPT command in teardown • Added 64-bit PCI BAR support • Added an option for running PXE with promiscuous VLAN • Added support for HII iSCSI configuration • Enlarged the mailbox size to 4kb • Enlarged the number of WQE to 64 (from 4) • Enabled multiple DHCP offers to be received before proceeding to request state • Changed the size of the domain name array to 0xfd • Changed error print to debug print • Changed printed string when initializing devices • Kept the SAN connection permanently open to enable Windows install on iSCSI target even when the iSCSI target is empty • Re-added COMBOOT image support by default • Prevented a netdevice (VLAN) from opening/closing twice • Removed unsupported EQ event in Connect-IB® • Disabled the waiting time for link up on trunk net device when VLAN is enabled on a port • Fixed sync VLAN IRQ operation with trunk IRQ operation • Fixed iSCSI initiator's name retrieval from HII issue • Fixed an issue caused in dual port adapters, when the first port was already linked up with DHCP, and had received a TFTP address. Booting from the second port resulted in TFTP download failure. • Fixed retry issue when the value is infinite • Fixed a TLV with length 0 issue • Fixed a PXE boot failure issue occurred when using a filename when iSCSI rootpath is set • Fixed "Impossible to PXE boot from 2nd port if first port already downloaded." issue • Fixed compilation issue • Fixed broken VLAN support issues
Rev 3.4.151	<ul style="list-style-type: none"> • Enlarged the mailbox size to 4kb • Enlarged the number of WQE to 64 (from 4) • Enabled multiple DHCP offers to be received before proceeding to request state
Rev 3.4.146	<ul style="list-style-type: none"> • Fixed memory corruption issues • Modified TLV flash access • Added additional WQ
Rev 3.4.142	<ul style="list-style-type: none"> • Enabled firmware to handle the link state with the Subnet Manager • Updated the DHCP class code to NONE • Added flash access capability for reading software-to-software configurations • Enabled DHCP validation of MAC address and XID for a unique tuple • Improved randomness algorithm for DHCP XID

Table 11 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.112	<ul style="list-style-type: none"> • Broadcast responses for firewall support • Enabled request broadcast responses from DHCP server to support firewall.
Rev 3.4.100	<ul style="list-style-type: none"> • OCSD activation initiation change • Moved the OCSD activation initiation from the FlexBoot to the CLP code. This enables the OCSD activation to no longer be dependent on the FlexBoot being enabled in the servers's BIOS configuration. • Messages' improvement • Made the FlexBoot on-screen notification messages more informative and user friendly. • FlexBoot and CLP merge improvement • Improved the process of merging the FlexBoot and CLP codes together. • PXE and UFI merge capability • Added the ability to merge the PXE image with a UFI image. • Supported servers • Added FlexBoot support capabilities to several new non-HP servers. • Use of newer iPXE version • Moved to use a newer iPXE version as the basis for the Flexboot release. • Fixed "no more network devices" issues during Flexboot.