



Connect. Accelerate. Outperform.™

MellanoxConnectX-3 Pro Firmware Release Notes

Rev 2.36.5000

NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT (“PRODUCT(S)”) AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES “AS-IS” WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER'S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies
 350 Oakmead Parkway Suite 100
 Sunnyvale, CA 94085
 U.S.A.
www.mellanox.com
 Tel: (408) 970-3400
 Fax: (408) 970-3403

© Copyright 2016. Mellanox Technologies. All Rights Reserved.

Mellanox®, Mellanox logo, BridgeX®, CloudX logo, Connect-IB®, ConnectX®, CoolBox®, CORE-Direct®, GPUDirect®, InfiniHost®, InfiniScale®, Kotura®, Kotura logo, Mellanox Federal Systems®, Mellanox Open Ethernet®, Mellanox ScalableHPC®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, Open Ethernet logo, PhyX®, SwitchX®, TestX®, The Generation of Open Ethernet logo, UFM®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

Accelio™, CyPU™, FPGADirect™, HPC-X™, InfiniBridge™, LinkX™, Mellanox Care™, Mellanox CloudX™, Mellanox Multi-Host™, Mellanox NEO™, Mellanox PeerDirect™, Mellanox Socket Direct™, Mellanox Spectrum™, NVMeDirect™, StPU™, Spectrum logo, Switch-IB™, Unbreakable-Link™ are trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

Table of Contents

Chapter 1	Overview	6
1.1	Supported Devices	6
1.2	Supported Cables and Modules	7
1.2.1	Validated and Supported 1GbE/10GbE Cables	7
1.2.2	Validated and Supported 20GB/s Cables	12
1.2.3	Validated and Supported 40GbE Cables	12
1.2.4	Validated and Supported QDR/FDR10 Cables	13
1.2.5	Validated and Supported FDR Cables	14
1.3	Tested Switches	15
1.4	Tools, Switch Firmware and Driver Software	19
1.5	Supported FlexBoot	20
1.6	Revision Compatibility	20
1.7	Firmware Burning Notes	20
Chapter 2	Firmware Rev 2.36.5000 Changes and New Features	21
Chapter 3	Known Issues	22
Chapter 4	Bug Fixes History	25
Chapter 5	Firmware Changes and New Feature History	34
Chapter 6	Flexboot Changes and New Features	38

List of Tables

Table 1:	Release Update History	5
Table 2:	Supported PSIDs	6
Table 3:	Validated and Supported 1GbE/10GbE Cables	7
Table 4:	Validated and Supported 20GB/s Cables	12
Table 5:	Validated and Supported 40GbE Cables	12
Table 6:	Validated and Supported QDR/FDR10 Cables	13
Table 7:	Validated and Supported FDR Cables	14
Table 8:	Tested Switches	15
Table 9:	Tools, Switch Firmware and Driver Software	19
Table 10:	Supported FlexBoot	20
Table 11:	Firmware Rev 2.36.5000 Changes and New Features	21
Table 12:	Known Issues	22
Table 13:	Fixed Bugs List	25
Table 14:	Firmware Changes and New Feature History	34
Table 15:	FlexBoot Changes and New Feature	38

Release Update History

Table 1 - Release Update History

Release	Date	Description
2.35.5100	January 31, 2016	Initial version of this firmware release

1 Overview

These are the release notes for the ConnectX-3 Pro adapters firmware Rev 2.36.5000. This firmware supports the following protocols:

- InfiniBand – SDR, DDR, QDR, FDR10, FDR
- Ethernet - 1GigE, 10GigE, 40GigE and 56GigE¹
- PCI Express 3.0, supporting backwards compatibility for v2.0 and v1.1

1.1 Supported Devices

This firmware supports the devices and protocols listed in [Table 2](#).

Table 2 - Supported PSIDs (Sheet 1 of 2)

Device Part Number	PSID	Device Name
MCX311A-XCCT	MT_1480111023	ConnectX®-3 Pro EN network interface card; 10GigE; single-port SFP+; PCIe3.0 x8 8GT/s; RoHS R6
MCX312B-XCCT	MT_1200111023	ConnectX®-3 Pro EN network interface card; 10GigE; dual-port SFP+; PCIe3.0 x8 8GT/s; RoHS R6
MCX312C-XCCT	MT_2340111023	ConnectX®-3 Pro EN network interface card, 10GbE, dual-port SFP+, PCIe3.0 x8 8GT/s, tall bracket, RoHS R6
MCX313A-BCCT	MT_1060111023	ConnectX®-3 Pro EN network interface card; 40GigE; single-port QSFP; PCIe3.0 x8 8GT/s; RoHS R6
MCX314A-BCCT	MT_1090111023	ConnectX®-3 Pro EN network interface card; 40GigE; dual-port QSFP; PCIe3.0 x8 8GT/s; RoHS R6
MCX349A-XCCN	MT_2330111004	ConnectX®-3 Pro EN network interface card, 10GBASE-T quad-port, PCIe 3.0 x8 8GT/s, RoHS R6
	MT_2330110004	
MCX353A-FCCT	MT_1100111019	ConnectX®-3 Pro VPI adapter card; single-port QSFP; FDR IB (56Gb/s) and 40GigE; PCIe3.0 x8 8GT/s
MCX354A-FCCT	MT_1090111019	ConnectX®-3 Pro VPI adapter card; dual-port QSFP; FDR IB (56Gb/s) and 40GigE; PCIe3.0 x8 8GT/s; RoHS R6
MCX341A-XCPN	MT_1270115023	ConnectX®-3 Pro EN network interface card for OCP, 10GbE single-port SFP+, PCIe3.0 x8, no bracket, RoHS R6
MCX341A-XCQN	MT_1270116023	ConnectX®-3 Pro EN network interface card for OCP, 10GbE, with IPMI and NC-SI, single-port SFP+, PCIe3.0 x8, no bracket, RoHS R6
MCX342A-XCPN	MT_1680115023	ConnectX®-3 Pro EN network interface card for OCP, 10GbE dual-port SFP+, PCIe3.0 x8, no bracket, RoHS R6

1. 56 GbE is a Mellanox propriety link speed and can be achieved while connecting a Mellanox adapter cards to Mellanox SX10XX switch series or connecting a Mellanox adapter card to another Mellanox adapter card.

Table 2 - Supported PSIDs (Sheet 2 of 2)

Device Part Number	PSID	Device Name
MCX342A-XCQN	MT_1680116023	ConnectX®-3 Pro EN network interface card for OCP with IPMI and NC-SI, 10GbE dual-port SFP+, PCIe3.0 x8, no bracket, RoHS R6
MCX345A-BCPN	MT_1740111023	ConnectX®-3 Pro EN network interface card for OCP, 40GbE single-port QSFP, PCIe3.0 x8, no bracket, RoHS R6
MCX345A-BCQN	MT_1740110023	ConnectX®-3 Pro EN network interface card for OCP, 40GbE, with IPMI and NC-SI, single-port QSFP, PCIe3.0 x8, no bracket, RoHS R6
MCX346A-BCPN	MT_1760111023	ConnectX®-3 Pro EN network interface card for OCP, 40GbE dual-port QSFP, PCIe3.0 x8, no bracket, RoHS R6
MCX346A-BCQN	MT_1760110023	ConnectX®-3 Pro EN network interface card for OCP; 40GbE; dual-port QSFP; PCIe3.0 x8; IPMI and NC-SI support; R6
MCX349A-XCCN	MT_2330111004	ConnectX®-3 Pro EN network interface card, 10GBASE-T quad-port, PCIe 3.0 x8 8GT/s, RoHS R6
	MT_2330110004	

1.2 Supported Cables and Modules

Please refer to the LinkX™ Cables and Transceivers web page (www.mellanox.com -> Products -> Cables and Transceivers) for the list of supported cables.

1.2.1 Validated and Supported 1GbE/10GbE Cables

This firmware was tested with the 10GbE/1GbE cables and modules listed in the table below.

Table 3 - Validated and Supported 1GbE/10GbE Cables (Sheet 1 of 5)

Speed	OPN #	Description
NA	MAM1Q00A-QSA	MELLANOX QSFP TO SFP+ ADAPTER
1GbE	453151-B21	HP BLc VC 1Gb SX SFP Opt Kit
1GbE	453154-B21	HP BLc VC 1Gb RJ-45 SFP Opt Kit
1GbE	MC3208011-SX	MELLANOX OPTICAL MODULE ETH 1GBE 1GB/S SFP LC-LC SX 850NM UP TO 500M
1GbE	MC3208411-T	MELLANOX MODULE ETH 1GBE 1GB/S SFP BASE-T UP TO 100M
10GbE	CAB-SFP-SFP-1M	passive copper cable, SFP+, 10 Gb/s, 1m
10GbE	CAB-SFP-SFP-2M	passive copper cable, SFP+, 10 Gb/s, 2m
10GbE	CAB-SFP-SFP-3M	passive copper cable, SFP+, 10 Gb/s, 3m

Table 3 - Validated and Supported 1GbE/10GbE Cables (Sheet 2 of 5)

Speed	OPN #	Description
10GbE	CAB-SFP-SFP-5M	passive copper cable, SFP+, 10 Gb/s, 5m
10GbE	XDL-TWX0101	Brocade passive copper cable, SFP+, 10 Gb/s, 1m
10GbE	XDL-TWX0301	Brocade passive copper cable, SFP+, 10 Gb/s, 3m
10GbE	XDL-TWX0501	Brocade passive copper cable, SFP+, 10 Gb/s, 5m
10GbE	SFP-H10GB-CU1M	Cisco SFP+ cable
10GbE	SFP-H10GB-CU3M	Cisco SFP+ cable
10GbE	SFP-H10GB-CU5M	Cisco SFP+ cable
10GbE	MC2309124-007	QSFP-4SFP10G
10GbE	SFP-10G-SR	CISCO 10GBASE-SR SFP Module
10GbE	MC2309124-007	QSFP-4SFP10G
10GbE	0NWGTV	SFP+ to SFP+ copper cable 1M
10GbE	0C4D08	SFP+ to SFP+ copper cable 1M
10GbE	0V250M	SFP+ to SFP+ copper cable 1M
10GbE	0NMMT9	SFP+ to SFP+ copper cable 1M
10GbE	053HVN	SFP+ to SFP+ copper cable 3M
10GbE	05CWK6	SFP+ to SFP+ copper cable 3M
10GbE	00F1VT9	SFP+ to SFP+ copper cable 3M
10GbE	00358VV	SFP+ to SFP+ copper cable 5M
10GbE	05CN56	SFP+ to SFP+ copper cable 5M
10GbE	0V492M	SFP+ to SFP+ copper cable 5M
10GbE	0W25W9	SFP+ to SFP+ copper cable 5M
10GbE	0J90VN	40GbE QSFP+ to QSFP+ copper cable 5M
10GbE	TCPM2	QSFP+ to 4xSFP+ copper cable 1M
10GbE	27GG5	QSFP+ to 4xSFP+ copper cable 3M
10GbE	P8T4W	QSFP+ to 4xSFP+ copper cable 5m
10GbE	0WTRD1	Dell 10Gb SR SFP+ Opt
10GbE	C4D08	Force 10passive copper cable, SFP+, 10 Gb/s, 1m
10GbE	53HVN	Force 10passive copper cable, SFP+, 10 Gb/s, 3m
10GbE	5CN56	Force 10passive copper cable, SFP+, 10 Gb/s, 5m
10GbE	J9281B	HP X242 10G SFP+ to SFP+ 1m Direct Attach Copper Cable

Table 3 - Validated and Supported 1GbE/10GbE Cables (Sheet 3 of 5)

Speed	OPN #	Description
10GbE	J9283B	HP X242 10G SFP+ SFP+ 3m DAC Cable
10GbE	J9285B	HP X242 10G SFP+ SFP+ 7m DAC Cable
10GbE	JD096B	HP X240 10G SFP+ SFP+ 1.2m DAC Cable
10GbE	JD095B	HP X240 10G SFP+ SFP+ 0.65m DAC Cable
10GbE	JD097B	HP X240 10G SFP+ SFP+ 3m DAD Cable
10GbE	JD096C	HP X240 10G SFP+ SFP+ 1.2m DAC Cable
10GbE	JD095C	HP X240 10G SFP+ SFP+ 0.65m DAC Cable
10GbE	JD097C	HP X240 10G SFP+ SFP+ 3m DAD Cable
10GbE	487649-B21	HP BLc SFP+ .5m 10GbE Copper Cable
10GbE	487652-B21	HP BLc SFP+ 1m 10GbE Copper Cable
10GbE	487655-B21	HP BLc SFP+ 3m 10GbE Copper Cable
10GbE	537963-B21	HP BLc SFP+ 5m 10GbE Copper Cable
10GbE	487658-B21	HP BLc SFP+ 7m 10GbE Copper Cable
10GbE	AP784A	HP 3m C-series Passive Copper SFP+ Cable
10GbE	AP785A	HP 5m C-series Passive Copper SFP+ Cable
10GbE	AP818A	HP 1m B-series Active Copper SFP+ Cable
10GbE	AP819A	HP 3m B-series Active Copper SFP+ Cable
10GbE	455883-B21	HP BLc 10Gb SR SFP+ Opt
10GbE	455886-B21	HP BLc 10Gb LR SFP+ Opt
10GbE	J9150A	HP X132 10G SFP+ LC SR Transceiver
10GbE	J9151A	HP X132 10G SFP+ LC LR Transceiver
10GbE	AJ839A	HP 50m Multi-mode OM3 LC/LC FC Cable
10GbE	AJ838A	HP 30m Multi-mode OM3 LC/LC FC Cable
10GbE	AJ837A	HP 15m Multi-mode OM3 LC/LC FC Cable
10GbE	AJ836A	HP 5m Multi-mode OM3 LC/LC FC Cable
10GbE	AJ834A	HP 1m Multi-mode OM3 LC/LC FC Cable
10GbE	AJ833A	HP 0.5m Multi-mode OM3 LC/LC FC Cable
10GbE	JG329A	HP X240 40G QSFP+ to 4x10G SFP+ 1m
10GbE	JG330A	HP X240 40G QSFP+ to 4x10G SFP+ 3m
10GbE	JG331A	HP X240 40G QSFP+ to 4x10G SFP+ 5m

Table 3 - Validated and Supported 1GbE/10GbE Cables (Sheet 4 of 5)

Speed	OPN #	Description
10GbE	JD095C	HP X240 10G SFP+ SFP+ 0.65m DAC Cable
10GbE	90Y9425-N28500A	IBM-Amphenol SFP+ 1m
10GbE	46K6184-L36836B	IBM-Amphenol SFP+ 5m
10GbE	46K6183-L36836B	IBM-Amphenol SFP+ 3m
10GbE	44X1371-N31295E	IBM-Amphenol SFP+ 7m
10GbE	95Y1634-N31295E	IBM SFP+ to SFP+ copper cable 5M
10GbE	44x1368-N31295E	IBM SFP+ to SFP+ copper cable 0.5M
10GbE	46K6182-L36836B	IBM SFP+ to SFP+ copper cable 1M
10GbE	46K6183-L36836B	IBM SFP+ to SFP+ copper cable 3M
10GbE	46K6184-L36836B	IBM SFP+ to SFP+ copper cable 5M
10GbE	QFX-SFP-DAC-1M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 1 m
10GbE	QFX-SFP-DAC-3M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 3 m
10GbE	QFX-SFP-DAC-5M	SFP+ 10 Gigabit Ethernet Direct Attach Copper (twinax copper cable) 5 m
10GbE	740-021308	Juniper 10GE SFP+ module
10GbE	MC2309124-004	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 4M
10GbE	MC2309124-005	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 5M
10GbE	MC2309124-006	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 6M
10GbE	MC2309124-007	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 7M
10GbE	MC2309130-001	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 1M
10GbE	MC2309130-002	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 2M
10GbE	MC2309130-003	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 3M
10GbE	MC2309130-00A	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE QSFP TO SFP+ 0.5M
10GbE	MC2609125-004	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 4M

Table 3 - Validated and Supported 1GbE/10GbE Cables (Sheet 5 of 5)

Speed	OPN #	Description
10GbE	MC2609125-005	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 5M
10GbE	MC2609130-001	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 1M
10GbE	MC2609130-002	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 2M
10GbE	MC2609130-003	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 3M
10GbE	MC2609130-0A1	MELLANOX PASSIVE COPPER HYBRID CABLE ETH 40GBE TO 4X10GBE QSFP TO 4X SFP+ 1.5M
10GbE	MC3309124-004	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 4M
10GbE	MC3309124-005	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 5M
10GbE	MC3309124-006	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 6M
10GbE	MC3309124-007	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 7M
10GbE	MC3309124-0A3	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 3.5M
10GbE	MC3309130-001	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 1M
10GbE	MC3309130-002	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 2M
10GbE	MC3309130-003	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 3M
10GbE	MC3309130-00A	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 0.5M
10GbE	MC3309130-0A1	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 1.5M
10GbE	MC3309130-0A2	MELLANOX PASSIVE COPPER CABLE ETH 10GBE 10GbE SFP+ 2.5M
10GbE	MFM1T02A-LR	Mellanox optical module, 1310nm, LR up to 10km
10GbE	MFM1T02A-SR	Mellanox optical module, 850nm, SR up to 300m
10GbE	MC6709309-050	Passive Optical Cable Multimode Splitter MPO To 8xlc 50 Meter

1.2.2 Validated and Supported 20GB/s Cables

This firmware was tested with the 20GB/s cables and modules listed in the table below.

Table 4 - Validated and Supported 20GB/s Cables

Speed	OPN #	Description
DDR	MC1204128-001	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 1M
DDR	MC1204128-003	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 3M
DDR	MC1204128-005	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 5M
DDR	MC1204130-002	MELLANOX PASSIVE COPPER HYBRID CABLE IB DDR 20GB/S QSFP TO CX4 2M

1.2.3 Validated and Supported 40GbE Cables

This firmware was tested with the 40GbE cables and modules listed in the table below.

Table 5 - Validated and Supported 40GbE Cables (Sheet 1 of 2)

Speed	OPN #	Description
40GbE	40GbE QSFP+ to QSFP	QSFP+ copper cable 3M
40GbE	40GbE QSFP+ to QSFP	QSFP+ copper cable 5M
40GbE	QSFP-H40G-CU1M	Cisco QSFP 40GbE cable
40GbE	QSFP-H40G-CU3M	Cisco QSFP 40GbE cable
40GbE	QSFP-H40G-CU5M	Cisco QSFP 40GbE cable
40GbE	QSFP-40G-SR4	CISCO 40G QSFP Module
40GbE	05NP8R	40GbE QSFP+ to QSFP+ copper cable 1M
40GbE	00FC6KV	40GbE QSFP+ to QSFP+ copper cable 3M
40GbE	0RF2MY	Dell 40GbB QSFP module
40GbE	10093084-200AHFLF	FCI QSFP 0.75m 40GbE cable
40GbE	10093084-2005HFLF	FCI QSFP 0.5m 40GbE cable
40GbE	10093084-2010HFLF	FCI QSFP 1m 40GbE cable
40GbE	NWGTV	Force 10passive copper cable, QSFP, 40 Gb/s, 1m
40GbE	V492M	Force 10passive copper cable, QSFP, 40 Gb/s, 5m
40GbE	GP-QSFP-40GE-1SR	Force10 - Dell 40GbB QSFP module
40GbE	JG325B	HP X140 40G QSFP+ MPO SR4 Transceiver

Table 5 - Validated and Supported 40GbE Cables (Sheet 2 of 2)

Speed	OPN #	Description
40GbE	JG325A	HP X140 40G QSFP+ MPO SR4 Transceiver
40GbE	JG326A	HP X240 40G QSFP+ QSFP+ 1m DAC Cable
40GbE	JG327A	HP X240 40G QSFP+ QSFP+ 3m DAC Cable
40GbE	JG328A	HP X240 40G QSFP+ QSFP+ 5m DAC Cable
40GbE	00D5802-N13445C	IBM 40GbE QSFP+ to QSFP+ copper cable 1M
40GbE	BN-QS-QS-CBL-3M	IBM 40GbE QSFP+ to QSFP+ copper cable 3M
40GbE	BN-QS-QS-CBL-5M	IBM 40GbE QSFP+ to QSFP+ copper cable 5M
40GbE	MC2210126-004	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GbE QSFP 4M
40GbE	MC2210126-005	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GbE QSFP 5M
40GbE	MC2210128-003	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GbE QSFP 3M
40GbE	MC2210130-001	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GbE QSFP 1M
40GbE	MC2210130-002	MELLANOX PASSIVE COPPER CABLE ETH 40GBE 40GbE QSFP 2M
40GbE	MC2210310-XXX	MELLANOX ACTIVE FIBER CABLE ETH 40GBE 40GbE QSFP from 3M up to 100M
40GbE	MC2210411-SR4L	MELLANOX OPTICAL MODULE 40GbE QSFP MPO 850NM UP TO 30M
40GbE	BN-CKM-QP-SR4	BN-CKM-QP-SR4 Blade 40GbB QSFP module

1.2.4 Validated and Supported QDR/FDR10 Cables

This firmware was tested with the QDR/FDR10 cables and modules listed in the table below.

Table 6 - Validated and Supported QDR/FDR10 Cables (Sheet 1 of 2)

Speed	OPN #	Description
FDR10	MC2206128-004	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 4M
FDR10	MC2206128-005	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 5M
FDR10	MC2206130-001	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 1M

Table 6 - Validated and Supported QDR/FDR10 Cables (Sheet 2 of 2)

Speed	OPN #	Description
FDR10	MC2206130-002	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 2M
FDR10	MC2206130-003	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 3M
FDR10	MC2206130-00A	MELLANOX PASSIVE COPPER CABLE VPI UP TO 40GbE QSFP 0.5M
FDR10	MC2206310-XXX-E	MELLANOX ACTIVE FIBER CABLE IB QDR/FDR10 40GbE QSFP from 3M up to 100M
FDR10	MC2206310-XXX-T	MELLANOX ACTIVE FIBER CABLE IB QDR/FDR10 40GbE QSFP from 3M up to 100M
FDR10	MC2206310-XXX-F	MELLANOX ACTIVE FIBER CABLE IB QDR/FDR10 40GbE QSFP from 3M up to 100M
FDR10	MC2206310-300-L	MELLANOX ACTIVE FIBER CABLE IB QDR/FDR10 40GbE QSFP 300M
FDR10	MC2210411-SR4	MELLANOX OPTICAL MODULE 40GbE QSFP MPO 850NM UP TO 100M
FDR10	MC2210411-SR4E	MELLANOX OPTICAL MODULE 40GbE QSFP MPO 850NM UP TO 300M
FDR10	MFS4R12CB-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 40GbE QSFP from 3M up to 100M
QDR	MC2206125-007	MELLANOX PASSIVE COPPER CABLE IB QDR 40GbE QSFP 7M
QDR	MC2206126-006	MELLANOX PASSIVE COPPER CABLE IB QDR 40GbE QSFP 6M

1.2.5 Validated and Supported FDR Cables

This firmware was tested with the FDR cables and modules listed in the table below.

Table 7 - Validated and Supported FDR Cables (Sheet 1 of 2)

Speed	OPN #	Description
FDR	038-004-066-01	EMC FDR QSFP+ to QSFP+ copper cable 2M
FDR	038-004-067-01	EMC FDR QSFP+ to QSFP+ copper cable 3M
FDR	038-900-027-01	EMC FDR QSFP+ to QSFP+ copper cable 5M
FDR	038-900-030-01	EMC FDR QSFP+ to QSFP+ copper cable 8M
FDR	038-004-236-01	FDR QSFP+ to QSFP+ copper cable 0.5m
FDR	038-004-065-01	EMC FDR QSFP+ to QSFP+ copper cable 1M

Table 7 - Validated and Supported FDR Cables (Sheet 2 of 2)

Speed	OPN #	Description
FDR	038-004-069-01	EMC FDR QSFP+ to QSFP+ copper cable 5M
FDR	MC2207126-004	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 4M
FDR	MC2207128-003	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 3M
FDR	MC2207128-0A2	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 2.5M
FDR	MC2207130-001	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 1M
FDR	MC2207130-002	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 2M
FDR	MC2207130-00A	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 0.5M
FDR	MC2207130-0A1	MELLANOX PASSIVE COPPER CABLE VPI UP TO 56GB/S QSFP 1.5M
FDR	MC2207310-XXX-E	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M
FDR	MC2207310-XXX-T	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M
FDR	MC2207312-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 300M
FDR	MC220731V-XXX	MELLANOX ACTIVE FIBER CABLE VPI UP TO 56GB/S QSFP from 3M up to 100M
FDR	MC2207411-SR4L	MELLANOX OPTICAL MODULE IB FDR 56GB/S QSFP MPO 850NM UP TO 30M

1.3 Tested Switches

Table 8 - Tested Switches (Sheet 1 of 4)

Speed	OPN # /Name	Description
1/10GbE	Summit X650	Extreme 10GB ETH switch
10/40GbE	7050Q	16-port 40Gb Switch
10/40GbE	7050S	48-port 10Gb/40Gb Switch
10/40GbE	3064	48-port 10Gb/40Gb Switch
10/40GbE	S5000	10GbE switch

Table 8 - Tested Switches (Sheet 2 of 4)

Speed	OPN # /Name	Description
10/40GbE	S4810P-AC	48-port 10Gb/40Gb Switch
10/40GbE	ASF5900	HP 10GB ETH switch
10/40GbE	IBM G8264	IBM 10/40GB ETH switch
10/40GbE	Juniper EX3500	Juniper 10/40GB ETH switch
10/40GbE	MSX1024B-1BFS	SwitchX®-2 based 48-port SFP+ 10GbE, 12 port QSFP 40GbE, 1U Ethernet switch
100GbE	MSN2700-CS2R	Mellanox 32 Ports QSFP 100GE MNG Switch Eth W/ 2 Ps Standard Depth C2P Airflow
10GbE	Brocade 8000	Brocade 10GB ETH switch
10GbE	Nexus B22	Cisco Nexus B22 FEX Blade switch
10GbE	5548	Cisco 10GB ETH switch
10GbE	8024F	10GbE switch
10GbE	8132F	10GbE switch
10GbE	Force10 MXL	Dell Force10 MXL 10/40GbE Blade switch
10GbE	PTM	Dell 10GbE KR PTM
10GbE	8164F	10GbE switch
10GbE	Fujitsu 10GbE	Ethernet Switch 24 ports, 20xCX4 and 4xQSFP
10GbE	HP ProCurve 6600-24XG	24-port 10GbE switch
10GbE	Juniper EX2500	Juniper 10GB ETH switch
10GbE	Juniper EX4550	Juniper 10GB ETH switch
10GbE	MSX1016X-1BFR	SwitchX™ based 64-port SFP+ 10GigE, 1U Ethernet switch
10GbE	Nexus B22	Cisco Nexus B22 FEX Blade switch
10GbE	Force10 MXL	Dell Force10 MXL 10/40GbE Blade switch
10GbE	PTM	Dell 10GbE KR PTM
10GbE	516733-B21	HP ProCurve 6120XG 10GbE Ethernet Blade Switch
10GbE	6125XLG Blade Switch	HP 6125XLG 10/40G Ethernet Blade Switch
10GbE	538113-B21	HP 10GbE Pass-Through Module (PTM)
10GbE	B22	IBM B22 10 Gigabit Scalable Switch Module
10GbE	EN4093	IBM PureFlex System Fabric EN4093 10 Gigabit Scalable Switch Module
10GbE	Juniper QFX3500	Juniper 10GbE ETH switch

Table 8 - Tested Switches (Sheet 3 of 4)

Speed	OPN # /Name	Description
1Gb/s	7024F	1/10GbE switch
1Gb/s	2810-24G	HP 1GB ETH switch
1GbE	3020X	Cisco Catalyst 3020X 1GbE switch blade
1GbE	3020	Cisco Catalyst 3020 1GbE switch blade
1GbE	438030-B21	HP 1GbE switch module - GbE2c Layer 2/3 Ethernet Blade Switch
1GbE	6120G	HP ProCurve 6120G/XG 1GbE switch blade
40GbE	MSX1036B-1BFR	SwitchX™ based 36-port QSFP 40GigE 1U Ethernet
40GbE	7050QX	32-port 40Gb Switch
40GbE	3016	Cisco 40GB ETH switch
40GbE	3132Q	Cisco 40GB ETH switch
40GbE	S6000	32-port 40Gb Switch
40GbE	689638-B21	Mellanox SX1018HP Enet Switch 40G Ethernet
40GbE	IBM G8316	IBM 40GB RackSwitch G8316
40GbE	90Y3477	BM Flex System EN6131 40Gb Ethernet Switch
40GbE	JuniperQFX5100	Juniper40GB ETH switch
DDR	410398-B21	HP BLc 4X DDR IB Switch
DDR	Mellanox M2401G	Infiniscale III 24-Port 20Gb/s InfiniBand Switch for Dell M1000E Blade System
DDR	F-X430044	24-port DDR-Switch
DDR	9024	24-port DDR-Switch
DDR	F-X430044	DDR-Switch F-X430044
EDR	MSB7790-EB2F	Switch-IB(TM) based EDR InfiniBand Switch, 36 QSFP ports, non-blocking switching capacity of 7.2Tbps,
EDR	SB7700	Switch-IB(TM) based EDR InfiniBand Switch 36-port EDR 100Gb/s InfiniBand Switch
FDR	MSX6036F-1SFR	SwitchX based FDR InfiniBand Switch; 36 QSFP; Managed
FDR	SRDFSH36F-1BF	SwitchX based FDR InfiniBand Switch; 36 QSFP; Managed
FDR	CA07156-0221	IB FDR switch Module 18 ports for BX900
FDR	775144-001	SwitchX-2 based 18-port QSFP FDR 1U unmanaged InfiniBand switch; R6; compatible to HP Apollo racks

Table 8 - Tested Switches (Sheet 4 of 4)

Speed	OPN # /Name	Description
FDR	648311-B21	HP BLc 4X FDR IB Switch
FDR	90Y3452	IBM Flex System IB6131 Infiniband Switch
FDR	MSX6710-FB2F2	SwitchX®-2 based FDR InfiniBand 1U Switch, 36 QSFP+ ports, 2 Power Supplies (AC), x86 dual core, short depth, P2C airflow, Rail Kit, RoHS6
FDR	MSX6036F-1BFR	SwitchX™ based FDR InfiniBand Switch, 36 QSFP ports, 1 Power Supply, Short depth, Managed, PSU side to Connector side airflow, Rail Kit and RoHS6
FDR	Mellanox M4001F	SwitchX® 56Gb/s 16+16 port InfiniBand switch blade for the Dell M1000e Blade System
FDR	SX6710	Mellanox 36-port FDR 56Gb/s InfiniBand Switch
FDR	MSX6506	FDR-Switch system Orca MSX6506
FDR10	MSX6025T-1SFR	SwitchX™ based FDR10 Infiniband Switch, 36 QSFP ports, 1 Power Supply, Standard depth, Unmanaged, PSU side to Connector side airflow, Rail Kit and RoHS6
FDR10	Mellanox M4001T	SwitchX® 40GbE 16+16 port InfiniBand switch blade for the Dell M1000e Blade System
QDR	CA07156-0201	IB QDR switch Module 18 ports for BX900
QDR	489184-B21	HP BLc 4X QDR IB Switch
QDR	MIS5025Q-1SFC	InfiniScale® IV QDR InfiniBand Switch, 36 QSFP ports, 1 Power Supply, Unmanaged, PSU side to connector side airflow, Standard depth, Rail Kit and RoHS5
QDR	MIS5024Q-1BFR	InfiniScale® IV QDR InfiniBand Switch, 36 QSFP ports, 1 power supply, Unmanaged, PSU side to Connector side airflow, no FRUs, with rack rails, Short Depth Form Factor
QDR	QDR-Switch 4036	InfiniScale® IV QDR Mellanox Grid Director 4036 36-Port QDR ,InfiniBand Switch - Part ID: VLT-30011
QDR	Mellanox M3601Q	40GbE 16+16 port InfiniBand switch blade for the Dell M1000e Blade System
QDR	12300	36-Port 40Gb QDR Infiniband Switch, Management Module, Dual Power
QDR	MIS5030Q-2SFC	InfiniScale IV IS5030 36 ports QDR InfiniBand Switch
SDR	F-X430060	24-port SDR-Switch
SDR	F-X430060	SDR-Switch F-X430060

1.4 Tools, Switch Firmware and Driver Software

Firmware Rev 2.36.5000 is tested with the following tools, SwitchX® firmware, and driver software:

Table 9 - Tools, Switch Firmware and Driver Software

	Supported Version
MLNX_OFED	3.2-1.0.0/3.1-1.0.3
MLNX_EN (MLNX_OFED based code)	3.2-1.0.0/3.1-1.0.3
WinOF	5.20/5.10
VMware	1.9.9.4/1.8.2.4
MFT	4.3.0/4.1.0
MLNX-OS	<ul style="list-style-type: none"> • SwitchX: 3.4.3004 • Switch-IB: 3.4.3206 • Spectrum: 3.5.0530
Spectrum™ Firmware	13.300.328
SwitchX/SwitchX-2 Firmware	9.3.5080
Switch-IB Firmware	11.0202.126
InfiniScale 4 Firmware	7.4.3000
Linux Inbox Drivers	<ul style="list-style-type: none"> • RHEL5.9 • RHEL5.10 • RHEL5.11 • RHEL5.12 • RHEL6.0 • RHEL6.1 • RHEL6.2 • RHEL6.3 • RHEL6.4 • RHEL6.5 • RHEL6.6 • RHEL7.0 • RHEL7.1 • Ubuntu 12.04 • Ubuntu 14.04 • SLES11.2 • SLES11.3 • SLES12.0
Windows Inbox Driver	<ul style="list-style-type: none"> • 2008R2 • 2012 • 2012R2

1.5 Supported FlexBoot

Firmware Rev 2.36.5000 supports the following FlexBoot version:

Table 10 - Supported FlexBoot

	Supported Version
FlexBoot	3.4.718

1.6 Revision Compatibility

Firmware Rev 2.36.5000 complies with the following programmer's reference manual:

- *Mellanox Adapters Programmer's Reference Manual (PRM), Rev 2.1 or later*, which has Command Interface Revision 0x3. The command interface revision can be retrieved by means of the QUERY_FW command and is indicated by the field `cmd_interface_rev`.

1.7 Firmware Burning Notes

- Firmware Family Version (FFV)

As of firmware v2.30.8000, all firmware images have the FFV field populated. The FFV value is identical to the firmware version but in a different format.

FFV format example:

```
FW version:      2.30.8000
FFV:             02.30.80.00
```

- Updating EXP_ROM

Updating only the EXP_ROM (FlexBoot) for firmware images which contain FFV requires an additional MFT flag: `"-allow_rom_change"`

The following is an example for removing the EXP_ROM from the binary image using Flint (a Mellanox device located at PCI bus function 05:00.0):

```
$ flint -d 05:00.0 -allow_rom_change drom
```

2 Firmware Rev 2.36.5000 Changes and New Features

Table 11 - Firmware Rev 2.36.5000 Changes and New Features

Category	Description
Packet Steering	Enables steering packets to receive queues according to Ethertype matching (See PRM 2.1 for more information).
RX Arbiter	Adds support for additional rate values.
Performance counter for WQE fetch	Counters that count the number of repeated Send WQE cache look-ups that resulted in a miss.
Checksum Calculation on Image/ Device	Flint utility allows performing an MD5 checksum on the non-persistent sections of the firmware image. For further information, please refer to MFT User Manual .

3 Known Issues

The following table describes known issues in this firmware release and possible workarounds.

Table 12 - Known Issues

Index	Issue	Description	Workaround
1.	Downgrade to previous GA requires server reboot.	Downgrading from v2.30.8000 or later to an earlier version than 2.30.8000 requires server reboot.	Reboot the server.
2.	GUID ConnectX®-3 Ethernet adapter cards	On ConnectX-3 Ethernet adapter cards, there is a mismatch between the GUID value returned by firmware management tools and that returned by fabric/driver utilities that read the GUID via device firmware (e.g., using <code>ibstat</code>). <code>Mlxburn/flint</code> return <code>0xffff</code> as GUID while the utilities return a value derived from the MAC address. For all driver/firmware/software purposes, the latter value should be used.	N/A. Please use the GUID value returned by the fabric/driver utilities (not <code>0xffff</code>).
3.	SBR assertion	SBR should be asserted for a minimum of 50 milliseconds for the ConnectX-3 adapters	N/A
4.	PCIe	On Pilot1 SL230, PCIe link occasionally does not come up at Gen3 speed	Production SL230 should be used for PCIe Gen3 operation
5.	Kernel panic in SR-IOV with RH6.3 Inbox driver and VPI cards	RH6.3 Inbox driver causes kernel panic when SR-IOV is enabled on VPI cards due to driver compatibility issue.	Set the <code>"do_sense=false"</code> parameter in the <code>[IB_TAB]</code> in the INI of the VPI card
6.	Side band Management compatibility with SR-IOV	In advanced steering mode, side band management connectivity may be lost when having more than 8 QP per mcg.	N/A
7.	SR-IOV disabled in the BIOS	When SR-IOV is disabled in the system BIOS, a PCI issue is noticed in Ubuntu v12.04.3 with Linux kernel v3.8 which affects NICs of several manufacturers including Mellanox's, preventing them from operating.	Enable SR-IOV in the BIOS
8.	MFT locking of flash semaphore	MFT tools might leave the flash semaphore locked if the tool operation is forced stopped. The locked semaphore prevents the firmware from accessing the flash and causes firmware hang.	Clear the semaphore using MFT command: <code>'flint -clear_semaphore'</code>
9.	MC2210411-SR4 module with Cable Info MAD	Cable Info MAD reports a wrong cable info when using the MC2210411-SR4 module	N/A

Table 12 - Known Issues

Index	Issue	Description	Workaround
10.	PCIe failure on temperature shock 10C/min	Gen2 failure at temperature sweep up to 10C/min (for MT27518A1-FDIR-BV only).	N/A
11.	PCIe Gen2 link	PCIe Gen2 link unstable at temperature sweep of 10C/min for MT27518A1-FDIR-BV	N/A
12.	Bloom filter	Bloom filter is currently not supported.	N/A
13.	Firmware downgrade	When downgrading from firmware v2.11.0000 and using MFT 3.0.0-3, the following message is displayed due to the mlxconfig tool: You are trying to override configurable FW by non-configurable FW. If you continue, old FW configurations will be cleared, do you want to continue ? (y/n) [n] : y You are trying to restore default configuration, do you want to continue ? (y/n) [n] : y	N/A
14.	DMFS steering mode with IB in Linux	DMFS should not be enabled when working with InfiniBand on MLNX_OFED-2.0.3	Upgrade to MLNX_OFED-2.1-x.x.x or later
15.	ConnectX®-3 Pro virtual function device ID	ConnectX®-3 Pro VF device ID is presented the same as ConnectX®-3 VF device ID due to driver limitations.	Use the physical function device ID to identify the device.
16.	VPD read-only fields	VPD read-only fields are writable.	Do not write to read-only fields if you wish to preserve them
17.	Increasing SymbolErrorCounter	When working in VPI mode with port1 FDR and port2 40G, error counters misbehave and increase rapidly	N/A
18.	128 Byte CQ/EQ stride compatibility with sideband Management	Setting the device to 128Byte CQ/EQ stride will cause misbehavior of sideband management resulting in communication loss.	N/A
19.	128 Byte CQ/EQ stride	CQ and EQ cannot be configured to different stride sizes.	N/A
20.	VPI port protocol change on a port with sideband Management	Changing port protocol from ETH to IB on port with NCSI/IPMI enabled while the port is connected to ETH switch is not supported.	<ol style="list-style-type: none"> 1. Unplug the cable from the switch 2. Restart driver 3. Change the protocol via the appropriate tools.

Table 12 - Known Issues

Index	Issue	Description	Workaround
21.	Link Up time	Adapter card MCX349A-XCCN may experience longer linkup times of a few seconds with specific switches.	N/A
22.	Port identification	Adapter card MCX349A-XCCN does not respond to ethtool “identify” command (ethtool -p/--identify).	N/A
23.	RDP over IPv6	RDP over IPv6 is currently not functional.	Set the default RoCE mode in the software to RoCE v2 (also when not using RoCE)
24.	Unicast/Multi-cast sniffer	Sniffer QP cannot be removed from the regular rule after adding the QP with insertion scheme equals to “push to that rule”	N/A
25.	Boot Entry Vector (BEV)	Since only a single Boot Entry Vector (BEV) per PCI Physical Function is supported, disabling the first port causes the second port to disappear as well.	N/A
26.	Cables	The NIC does not notify the driver of a link-down incident when a cable is unplugged from a NIC port with 56GbE port link.	N/A
27.	Port Link	56GbE link is not raised when using 100GbE optic cables.	N/A

4 Bug Fixes History

Table 13 lists the bugs fixed in this release.

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
1.	ECN	Fixed a completion error issue when ECN was enabled. The ECN usage caused ordering errors in completion queues (CQ).	2.33.5000	2.36.5000
2.		Fixed the length calculation of UDP. The incorrect UDP length in the CNP packet caused miss-calculation of the ICRC.	2.35.5100	2.36.5000
3.	Cable Info MAD	Fixed a wrong returned status in cable info MAD when the cable was not connected.	2.35.5100	2.36.5000
4.	FLR device reset	Fixed failure instances when initiating FLR in the Physical Function.	2.35.5100	2.36.5000
5.	High rate steering mode	Disabled High Rate Steering mode in the INI to enable its compatibility with NC-SI over VLAN.	2.32.5100	2.36.5000
6.	RDP over IPv4	Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.	2.30.8000	2.35.5100
7.	SR-IOV security	Prevented a Virtual Function from injecting pause frames into the network.	2.30.8000	2.35.5100
8.	PRM:SET_PORT.macc_table	Fixed a wrong hash index calculation during inbound traffic.	2.33.5100	2.35.5100
9.	RDP over IPv4	Fixed a default hardware configuration issue which caused RDP over IPv4 traffic to be dropped.	2.30.8000	2.35.5100
10.	NC-SI	Fixed an issue causing MLNX_OEM command GET_TEMP to return a wrong value in the max_temp field	2.34.5000	2.35.5100
11.	MTU exceptions	Fixed an issue which caused TX traffic to stop when the message MTU size was larger than QP.mtu.	2.32.5100	2.35.5100
12.	NVCONFIG failure	Fixed an issue which caused NVCONFIG to fail when the number of sector was set to 1 and the sector was zeroed.	2.34.5000	2.35.5100
13.	IB/RoCE retransmission	Fixed a race in handling a duplicated “read request from middle”.	2.34.5000	2.35.5100

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
14.	IB traffic issues	Fixed an issue which caused lack of IB traffic on SR-IOV VPI.	2.33.5000	2.35.5100
15.	NVRAM issues	Fixed an issue which caused NVRAM to get stuck when it filled non-valid information in TLV.	2.34.5000	2.35.5100
16.	IB APM	Fixed an issue which caused an internal firmware error when APM changed the QPs port mapping.	2.33.5100	2.35.5100
17.	QP alternate context error	Fixed an issue which caused a firmware internal error when handling QP alternative context.	2.34.5000	2.35.5100
18.	Flow Control security issue	Fixed an issue which caused packet transmission to get stuck when the software tried to send pause frames with dmac equal to one of the device's MAC addresses.	2.32.5100	2.35.5100
19.	Wrong temperature reporting	Wrong temperature reporting when server is in Auxiliary mode after Moonshot AC power cycle.	2.34.5000	2.35.5100
20.	Link down on MCX-349A-XCCN	Fixed a link down issue with 100MbaseT speed.	2.33.5100	2.34.5000
21.	Packet Ethertype	Fixed a mistakenly dropped ETH packet with ethertype 0x600 by the NIC.	2.30.8000	2.34.5000
22.	Broadcast traffic lost	Fixed a case preventing broadcast traffic from arriving to their destination after detaching high priority broadcast rule on a port where NC-SI was enabled.	2.33.5100	2.34.5000
23.	RSS QP update failure	Fixed a failure to update RSS QP in steering rules.	2.33.5100	2.34.5000
24.	Low link speed	Fixed an issue where the port raised as SDR vs. InfiniScale IV QDR Switch	2.33.5100	2.34.5000
25.	40GbE Link down	Fixed a failure to read cable parameter which caused link failure on 40GbE dual port OCP devices.	2.33.5100	2.34.5000
26.	RDMA read retransmission	Fixed a rare case of completion Error with Bad Opcode sequence status which occurred when retransmitting read requests.	2.33.5100	2.34.5000
27.	VM QoS	Fixed a case where the actual bandwidth did not match the user settings in VM QoS.	2.33.5100	2.34.5000

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
28.	Sideband communication loss	Fixed a case where on rare cases, communication to BMC was lost during driver initialization.	2.33.5100	2.34.5000
29.	LED behavior	Fixed a wrong LED behavior when the driver is disabled in the following adapter cards: MCX346A-BCQN, MCX345A-BCQN.	2.33.5100	2.34.5000
30.	Link down on cable plugging	Fixed an issue with cable reading, which caused the link not to raise	2.33.5100	2.34.5000
31.	PRM: EQN range	Set the maximum EQN number to 1024.	2.30.8000	2.34.5000
32.	Vital Product Data read failure	Fixed a rare issue with VPD init flow which caused read failures.	2.31.5050	2.34.5000
33.	PRM: Statistic counters not reported	Fixed an issue with RX size counter not being reported.	2.30.8000	2.34.5000
34.	RoCE/InfiniBand reliable connection	The first Read response was not treated as implicit ACK.	2.30.8000	2.33.5100
35.	40GbE Link up time	Reduced a long 40GbE link up time with Cisco Nexus3064 and Arista-7050S	2.32.5100	2.33.5100
36.	Promiscuous mode	Fixed promiscuous mode compatibility with A0-DMFS steering.	2.32.5100	2.33.5000
37.		Fixed promiscuous mode compatibility when NC-SI is enabled and configured.	2.32.5100	2.33.5000
38.	NC-SI OEM commands	Fixed sending/receiving OEM temp commands (set/get) with channel ID 0x1f failure.	2.32.5100	2.33.5000
39.	Packet Drops	Fixed an issue which caused packets to drop on a port when changing the interface state of the other port.	2.32.5100	2.33.5000
40.	Side Band Functionality	Fixed long management communication loss and SOL hang during reboot cycles.	2.32.5100	2.33.5000
41.		Fixed wrong processing of inbound traffic towards BMC which caused communication loss.	2.32.5100	2.33.5000
42.		Fixed management link loss upon closing port interface through the driver.	2.32.5100	2.33.5000
43.	NC-SI on SFP+ Adapter Cards	Fixed a false indication in firmware of an expander presence causing delay in EEPROM reading.	2.32.5100	2.33.5000

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
44.	Port Links	Fixed an issue which caused a link down on a port when the cable was removed from the other port.	2.32.5100	2.33.5000
45.	Inbound Packet Processing	Fixed a rare case where packet with length zero got stuck in hardware queues.	2.32.5100	2.33.5000
46.		Fixed an issue which caused InfiniBand congestion control packet (CNP) to hang in hardware.	2.32.5100	2.33.5000
47.	Asynchronous Event Notification (AEN)	Fixed an issue which caused AEN to be sent after channel reset.	2.32.5100	2.33.5000
48.	Bandwidth Degradation with QoS	Fixed an issue which prevented the restoring of QoS setting to its default consequently causing bandwidth degradation.	2.31.5050	2.33.5000
49.	Port Link Up Time	Fixed an occasional long link up time with 10GbE based devices.	2.32.5100	2.33.5000
50.	SFP Cable Reading	Fixed an issue preventing cable readings from i2c slave address 0x51	2.32.5100	2.33.5000
51.	PCIe Gen3 Equalization	Fixed a wrong parity bit calculation when transmitting PCIe TS1 packets.	2.32.5100	2.33.5000
52.	PCIe Power Management	Fixed a possible deadlock in PM turnoff request transmission and ack acceptance flow.	2.32.5100	2.33.5000
53.	PCIe width Degrade	Fixed a rare case with alignments state machines which caused occasional width degradation.	2.32.5100	2.33.5000
54.	Rate Limiters Hang with ECN/QCN Enabled	Fixed an issue where the transmit queues hanged while congestion control was enabled and operational (EQC/QCN)	2.32.5100	2.33.5000
55.	Unexpected Completion Syndrome with Status 0x77	Fixed an unexpected work completion syndrome with vendor syndrome 0x77 received when running RDMA SEN/WRITE traffic with retransmissions.	2.30.8000	2.33.5000
56.	IB Spec MADs	Fixed an issue which caused <code>SetPortInfo</code> to return a good status when receiving invalid <code>LinkSpeedEnabled</code> value.	2.32.5100	2.33.5000
57.	GPIO Mapping	Fixed an issue which caused dual port SFPP module cards to be automatically mapped with expander	2.32.5100	2.33.5000

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
58.	Steering Mode	Fixed an issue where firmware overrides the steering mode that was chosen by the driver.	2.32.5100	2.33.5000
59.	Port sensing	Fixed invalid return sensing results occurred when the link was up.	2.32.5100	2.33.5000
60.		Fixed an issue causing the sensing result to be delayed when cable was unplugged.	2.32.5100	2.33.5000
61.	Wrong link type display	Fixed an issue causing the link type to be displayed as ETH when set to AUTO.	2.32.5100	2.33.5000
62.	WoL Functionality	Fixed 2us glitch in Wake Up signal.	2.32.5100	2.33.5000
63.	IBDump performance	Fixed performance degradation when running IBDump	2.30.8000	2.32.5100
64.	PCIe link Disable/Enable	Occasionally, a link training timeout occurred in EQ phase0 during disable/enable test.	2.31.5050	2.32.5100
65.	40GbE QoS	Improved strict bandwidth mode functionality	2.30.8000	2.32.5100
66.	Port Counters reporting	Fixed an issue with the PortRevPkts counter always displaying zero value.	2.31.5050	2.32.5100
67.	GMP MADs in SecureHost	Fixed an issue with processing GMP MADs with SET method in SecureHost mode.	2.31.5050	2.32.5100
68.	NC-SI over IPv6	Fixed an issue causing a wrong usage of MCG size when configuring Global Multicast filter	2.31.5050	2.32.5100
69.	NC SI link failure	Disabling the first port occasionally causes second port TX failure.	2.31.5050	2.32.5100
70.	10GbE link failure	Fixed a mismatch in links status reported. The adapter reports links as down while the switch perceives them as up	2.31.5050	2.32.5100
71.	Link failure	Fixed an occasional 40GbE link failure with SCM5 Switch blade	2.31.5050	2.32.5100
72.	ExtPortInfo MAD	Fixed a wrong FDR10 speed reporting in MAD	2.31.5050	2.32.5100
73.	IB link failure	Fixed an issue preventing theports to to rise up when set to FDR10 vs QDR	2.31.5050	2.32.5100
74.	40GbE link failure	Fixed an occasional link failure vs Arista switch	2.31.5050	2.32.5100

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
75.	RDMA Write retransmission	Retransmission started from the first PSN of message instead of the last acknowledged PSN	2.30.3200	2.32.5100
76.	Firmware burning	Firmware hangs when receiving <code>GeneralInfoMad</code> during inline firmware burning	2.30.3200	2.32.5100
77.	PCIe PML1	L1 flow adjustments and threshold tuning	2.31.5050	2.32.5100
78.	PCIe reset	Fixed a rare hanging issue during <code>PERST_assertion</code>	2.31.5050	2.32.5100
79.	PCIe Gen3 EQ	Wrong coefficients were reported during <code>phase3</code>	2.31.5050	2.32.5100
80.	Boot	Fixed an issue causing wrong behavior due to reset timing	2.31.5050	2.32.5100
81.	VXLAN/NVGRE	Fixed lack of steering options	2.30.8000	2.32.5010
82.	SMBUS	Fixed long timeout issues	2.31.5050	2.32.5100
83.	NVRAM	Fixed NVRAM write issues in driver-less mode	2.31.5050	2.32.5100
84.	40GbE Link support	Fixed 40GbE link support in aux mode	2.31.5050	2.32.5100
85.	NC-SI	Dropped commands with non-existing channel ID	2.31.5050	2.32.5100
86.	PRM PortInfo command	Fixed issues in extended speed reporting	2.31.5050	2.32.5100
87.	Trap 257/8(IB)	Fixed bad QP reporting in trap 257/8	2.30.8000	2.32.5100
88.	Bad Q_KEY errors	Fixed an issue causing false bad <code>q_key</code> error messages	2.30.8000	2.32.5100
89.	PFC	Fixed Pause Frame opcode mismatch	2.30.8000	2.32.5100
90.	Sideband Communication	Fixed communication loss upon PCIe error detection	2.31.5050	2.32.5100
91.	NC-SI	Fixed wrong channel value in the <code>SELECT/DESELECT PACKAGE</code> commands	2.30.8000	2.31.5050
92.		Fixed an issue caused response packet to include 4 extra bytes	2.30.8000	2.31.5050
93.		Fixed wrong reason code value returned when using <code>Set Link</code> command with unsupported speed.	2.30.8000	2.31.5050
94.		Added protection from bad MAC address given by BMC	2.30.8000	2.31.5050

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
95.	False Link Indication	Fixed an issue causing the device to report false link up when no cable is connected.	2.30.8000	2.31.5050
96.	PCIe	Removed false TX pulse after PERST_ deassertion	2.30.8000	2.31.5050
97.		Fixed FLR capability bit inconsistency when SR-IOV is enabled.	2.30.8000	2.31.5050
98.		Fixed an issue with the device not reporting PCIe related errors.	2.30.8000	2.31.5050
99.	SDR instead of DDR ConnectX-3 to SX6036	When a link is configured to DDR in a setup of ConnectX-3 to SX6036, SDR link is established instead.	2.30.8000	2.31.5050
100.	VXLAN	VXLAN used the wrong default UDP port. the UDP port number was changed to 4789.	2.30.8000	2.31.5050
101.		Fixed wrong setting of the UDP destination port for VXLAN.	2.30.8000	2.31.5050
102.	Flow Steering	Fixed an internal error caused when moving to the DMS mode with IPMI/NC-SI enabled.	2.30.8000	2.31.5050
103.	FDR speed degradation with 0.5m cables	In a back-to-back setup of FDR cards connected with a 0.5m FDR cable, a link may be established as FDR10 instead of FDR.	2.30.8000	2.31.5050
104.	PCI interrupt	Fixed issues related to working with PCI legacy interrupts.	2.30.8000	2.31.5050
105.	TCP/UDP Checksum	Fixed wrong checksum calculation for short packets which were padded by the software.	2.30.8000	2.31.5050
106.	MFT tool deadlock	Reading PCIe configuration space after using the MFT flint tool caused the device to crash.	2.30.8000	2.31.5050
107.	Side band packet loss	Fixed occasional packet loss over IPMI	2.30.8000	2.31.5050
108.	Eye opening MAD	Fixed wrong values reported in the Eye opening MAD.	2.30.8000	2.31.5050
109.	PCIe Link width	Fixed occasional link width degrades during link negotiation and link transitions from L1 state.	2.30.8000	2.31.5050
110.	PCIe signal detect	Fixed adjust signal detect thresholds	2.30.8000	2.31.5050
111.	Error counters	PortExtendedSpeedsCounters MAD counters were mistakenly increased while LLR was active	2.30.8000	2.31.5050

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
112.	PCIe Gen3 Equalization	Lane reversal was not considered when configured TX parameters	2.30.8000	2.31.5050
113.	Reset On LAN (ROL)	Fixed ROL factory MAC usage when a FlexBoot address was given.	2.30.8000	2.31.5050
114.	Flow Control	Fixed Pause frames factory MAC usage when a FlexBoot address was given.	2.30.8000	2.31.5050
115.	WOL/ROL	The device did not different between WOL/ROL packets.	2.30.8000	2.31.5050
116.	PortInfo MAD	Fixed a set of extended fields in PortInfo MAD which did not function.	2.30.8000	2.31.5050
117.	LLR cell size	Adjusted LLR cell size according to the MLPN negotiation of ib_128b_llr	2.30.8000	2.31.5050
118.	Link max speed	The max speed restriction was active in full power mode instead of standby mode only.	2.30.8000	2.31.5050
119.	InfiniBand Automatic Path Migration	The InfiniBand Path migration did not work with GRH. http://webdev01:8080/commit/ConnectX.git/a9c37ee4c31038f2c1179d4d9e79c9337e0ab5c7	2.30.8000	2.31.5050
120.	Packet steering	Reading MGM after writing it returned wrong members count.	2.30.8000	2.31.5050
121.	RSS QP context	Fixed corruption of the RSS hash key given by the driver.	2.30.8000	2.31.5050
122.	10Gb/s QoS	Fixed QoS rate limit bandwidth offset.	2.30.8000	2.31.5050
123.	ExtendedPortInfo MAD	Fixed FDR10 speed_en reporting.	2.30.8000	2.31.5050
124.	Management link	Fixed long management link com loss.	2.30.8000	2.31.5050
125.	PRM Query_Port Command	The command results reported both link types active at the same time.	2.30.8000	2.31.5050
126.	Link not raising	Fixed collision between forcing phy type and port sensing.	2.30.8000	2.31.5050
127.	Core clock reporting	Fixed a wrong core clock freq reporting in QUERY_HCA command.	2.30.8000	2.31.5050
128.	56GbE link issues	Fixeds occasional link failure when 56GbE is enabled	2.30.8000	2.31.5050
129.	RX calibration	Fixed max eye margins to be per protocol.	2.30.8000	2.31.5050

Table 13 - Fixed Bugs List

Index	Issue	Description	Discovered in Release	Fixed in Release
130.	VPI symbol errors	perfquery reported wrong error symbol on ConnectX [®] -3 VPI mode: IB, ETH.	2.30.8000	2.31.5050
131.	Symbol error on ConnectX-3 Pro dual-port QDR with MC2207312-030 AOCs	On ConnectX-3 Pro dual-port QDR and FDR/FDR10 switch setups, symbol errors may occur with MC2207312-030 AOCs.	2.30.8000	2.31.5050
132.	Symbol error on Falcon QDR against FDR switches with MC2207126-004 copper cables	Symbol errors occur on ConnectX-3 Pro dual-port QDR connected to FDR switches with MC2207126-004 copper cables.	2.30.8000	2.31.5050
133.	Changing from an LLR to non-LLR requires driver restart	Driver restart required when switching from InfiniBand FDR link with LLR enabled to InfiniBand link w/o LLR (for example: between SwitchX [®] and GD4036).	2.30.8000	2.31.5050
134.	40GbE link up issue	On rare occasions, the adapter card may fail to link up when performing parallel detect to 40GbE.	2.30.8000	2.30.8050
135.	Automatic Path Migration (APM)	Automatic Path Migration (APM) did not update the new MGIDs from the Alternate Path.	2.30.8000	2.30.8050

5 Firmware Changes and New Feature History

Table 14 - Firmware Changes and New Feature History

Firmware Version	Description
2.35.5100	<ul style="list-style-type: none"> • New performance and back-pressure counters command via PRM (For further information, please refer to the PRM) • Support for Multicast/Unicast sniffer rules (For further information, please refer to the PRM) • Support for VLAN in VLAN encapsulation (For further information, please refer to the PRM) • CQ creation offload by software • Support for rst2rts command • Invalidates a TLV during the firmware boot stage • A new counter for the <code>diag_rprt</code> PRM command to count packet drops due to no-receive buffer • Support for Ethernet TX lifetime cycle control (Head of Queue) • A new register (PPLR) that allows egress and external loopback control (For further information, please refer to the PRM) • A watchdog mechanism to track ingress traffic stalls to prevent flooding the network with Flow Control packets • Inspur LED scheme: A new LED scheme controlled by the INI which causes constant traffic LED indication even without traffic.
2.34.5000	<ul style="list-style-type: none"> • Added support for multiple RoCE modes (RoCE v1+v2) on the same port: RoCE mode is per connection now. • Added a new QP command "<code>INIT2RTS_QP</code>" to enhance QP connection readiness time. • Disabled FCS checks to support switches that replace FCS with Timestamp. • Added RX Port identification for direct rout packets. • Improved RDMA WRITE/SEND performance with retransmissions. • Enabled firmware burning/querying using the PRM <code>ACCESS_REG</code> command. • Added support for VAM. • Enabled bad cable EEPROM reporting to the driver. • Added support for Platform Level Data Model (PLDM) sideband protocol. • Added support for priority based A0-DMFS mode (For further information, please refer to the PRM). • Added support for Unicast/Multicast loopback disablement by the driver. (For further information, please refer to the PRM) • Removed the source IP from the hash calculation (For further information, please refer to the PRM) • Added support for Inline Receive mode up to 2KB.
2.33.5100	<ul style="list-style-type: none"> • Enabled ConnectX®-3 Pro to work in packet parsing mode to enable checksum calculation of non-TCP/UDP packets. • Bug fixes - see "Bug Fixes History" on page 25

Table 14 - Firmware Changes and New Feature History

Firmware Version	Description
2.33.5000	<ul style="list-style-type: none"> • Enabled ConnectX-3 Pro to work in packet parsing mode to enable checksum calculation of non TCP/UDP packets. • Bandwidth allocation support: Including maximum bandwidth and bandwidth share guarantee between VMs for InfiniBand and Ethernet. • Increased inbound traffic buffer capacity when the PFC on all priorities is enabled. • Added support for changing UAR BAR (PCI BAR 2) size. • Added support for cable sub-power class for Mellanox MFA1A00-EXXX and SMFA1A00-CXXX EDR cables. • Improvements in attachment/detachment flows' rules in both A0-DMFS and DMFS modes. • Added physical port forcing on specific QPs when virtual mapping is applied • Added support for dynamic enablement of LAG mode • Added support for vendor specific command to report the ports' MAC addresses. • Enabled 100Mb ability exposure and its enablement via an INI parameter. • Added support for SFP+ with 1GbE when the adapter card is enabled in the EEPROM. • Optimized the SideBand connectivity loss during driver initialization to minimum. • Added support for SMBUS ARP. • Enabled thermal reporting of TMP421 sensor in OCP cards. • RDMA Read retransmission optimizations to improve performance and ensure forward progress while packet drops occur. • Improved data path WQE prefetch algorithm.

Table 14 - Firmware Changes and New Feature History

Firmware Version	Description
2.32.5100	<ul style="list-style-type: none"> • Added support to query PTYS, PTOS registers through ACCESS_REG PRM command. • Added support for CLP access to NVRAM • Added support for more than 22 QPs per MCG in DMFS. • Added support for high rate steering mode (a.k.a Simplified Steering) • Added support for reading current hardware mode through the QUERY_PORT PRM command • Added CSUM mode reporting in QUERY_DEV_CAP command • Added additional configuration options for UPDATE_QP command • Added support for 128 Byte stride for CQ/EQ • Enabled module EEPROM access using command I/F • Reset Flow improvements and graceful handling of error caused by Virtual Functions • RX performance optimization for single port cards • Promiscuous mode performance improvements • Added support for Secure Host mode • Added Port protocol configuration option. • Added support for GPIO swap • 40GbE SI improvements • Added support for Temp Sensing Vendor specific MAD. • Added Temp Sensing NC-SI cmd. • Added support for AEN. • Added new command to report firmware revision. • Added support for QCN • Enabled the driver to use VXLAN offloads on TX side without Device Managed Flow Steering (DMFS) • Enabled non Mellanox cables to rise FDR10 link via new INI parameter. To unlock the cables run: <code>Fdr10_cable_stamping_override</code>
2.31.5050	<ul style="list-style-type: none"> • Added support for GeneralInfo SMP MAD • Updated capability mask in GeneralInfo SMP/GMP MAD • Added support for PortCountersVL MAD • Added support for PortSamplesControl/PortSamplesResults/PortSamplesExtended MADs • Added Exponential Backoff Timer support. It is enabled via the <code>rtm_ini</code> parameter. The default value is 0 • Added VLAN steering to Device Managed Flow Steering (DMFS) • Added support for Non-Volatile configuration of TLVs to set device attributes: <ul style="list-style-type: none"> • Query and set of configurations is available through PRM ACCESS_REG command • PRM ACCESS_REG command is now also supported through the <code>tools_hcr</code> command interface • Added support for MTF mlxconfig tool • Added IPv6 support for NC-SI and IPMI Pass-Through • Added support for the same unicast MAC simultaneously for both IPMI and NC-SI • PCIe power optimizations for 8X/4X links • SMBUS optimizations

Table 14 - Firmware Changes and New Feature History

Firmware Version	Description
2.31.5050 (cont.)	<ul style="list-style-type: none"> • Added enhancements for receiver equalization in Gen3: <ul style="list-style-type: none"> • Enhancements are enabled by the INI. The default value is disabled. Please contact Mellanox support if required to enable it. • Added new Physical and Virtual Functions reset flows support • Added support for 64Bit BIOS mode • Added IEEE802.3 CL73 autoneg support to the QUERY_PORT command. • Added factory MAC address reporting to the Query_Port command. • Added support for reverting virtual MAC configuration per port and restoring to factory MAC through MOD_STAT_CFG command. • Added support for inline TLV read through MOD_STAT_CFG command. • Added current MTU reporting to the QUERY_PORT command. • Added support query for additional MAC addresses per port (up to 7) through the QUERY_PORT command.
2.30.8050	<ul style="list-style-type: none"> • Bug fixes - see “Bug Fixes History” on page 25
2.30.8000	<ul style="list-style-type: none"> • Initial GA release of ConnectX-3 Pro • UDP packets with zero checksum • RoCE v2 support, including CONFIG_DEV command support • Enabled SR-IOV by default on all Mellanox ConnectX-3 Pro cards with 8 virtual functions • indiscard packets counter support in DUMP_ETH_STAT command • NVGRE support • VXLAN support • DMFS and GRE steering: Rule insertion adjustments • Removed DIF support from reported capabilities in QUERY_DEV_CAP PRM command • Flow control by DSCP priority for IPv4 • DMFS improvements: Insertion scheme enforcement and block loopback for InfiniBand • Added I2C resiliency support • Support for NC-SI over MCTP over SMBus • Added a flash access interface for persistent (non-volatile) configuration support • Added port BW arbitration configuration through the CONFIG_DEV command • Added IP-in-IP TCP checksum offload support • PCI Express compliancy Tx and Rx adjustments • Removed software limitations that were required for the use of Mellanox-certified FDR InfiniBand cables with Mellanox FDR InfiniBand adapters and switches. Please refer to "Memo: FDR 56Gb/s InfiniBand Cables" that was released on Dec/2013. <p>Mellanox will offer an EXTENDED diagnostics support plan which will be available for mixed environments only and that will help identify issues they may encounter with the FDR installations.</p>
2.30.8000 (cont.)	<ul style="list-style-type: none"> • Added support for 40GbE in WoL and pre-OS driver modes To enable this, add/change the following flags in the INI file in the IB and HCA tabs respectively: <ul style="list-style-type: none"> • <code>restrict_max_eth_standby_speed = NO_RESTRICTION</code> • <code>slow_clock_enable = 0</code> • Bug fixes - see “Bug Fixes History” on page 25

6 Flexboot Changes and New Features

For further information, please refer to FlexBoot Release Notes (www.mellanox.com > Software > InfiniBand/VPI Drivers > FlexBoot).

Table 15 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.718	<ul style="list-style-type: none"> • Added IPv6 support (Beta level) • Removed support for the following SHELL CLI commands: <ul style="list-style-type: none"> • Non-volatile option storage commands • SAN boot commands • Menu commands • Login command • Sync command • DNS resolving command • Time commands • Image crypto digest commands • Loopback testing commands • VLAN commands • PXE commands • Reboot command <p>For further information, please refer to: http://ipxe.org/cmd</p>
Rev 3.4.648	<ul style="list-style-type: none"> • Added support for .mrom images larger than 128kB • Added boot over IB with non-default PKey for ConnectX®-3, ConnectX®-3 Pro cards • Added support for ConnectX-4 and ConnectX-4 Lx • Synced the source with iPXE (upstream sync) • Moved to flat real mode when calling INT 1a,b101 to avoid BIOSes issues • Fixed chainloading undionly.kpxe over Connect-IB functionality • Fixed HTTP boot over IPoIB
Rev 3.4.521	<ul style="list-style-type: none"> • Added iSCSI CHAP and mutual CHAP configuration • Added the GRH size when allocating receive buffer for IPoIB • Updated VLAN netdevice's settings with all the trunk's iSCSI required settings • Updated the port event handling process • Enabled console output in Debug mode • Disabled the serial output • Disabled the banner in BEV execution • Disabled function 0x04 (in int21) when serial console is disabled • Preserved COM port settings • Fixed HTTP download over IPoIB • Fixed completion with error handling process

Table 15 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.460	<ul style="list-style-type: none"> • Boot Menu support: Added new FlexBoot GUI. The device can now be configured in the POST stage. • Non volatile memory read/write support • Configurable URI boot retry and delay between retries • Configurable iSCSI settings using DHCP/NVM • Added new interface in order to update the registered devices on the PXE stage • Enabled ConnectX Ethernet adapter cards family to work with interrupts • Enabled PXE to work in promiscuous VLAN mode (configurable through the INI) • Synced version with ipxe.org: Now the latest code in iPXE is used • Added boot priority capability: iSCSI vs PXE and fallback incase one fails • Updated the Proxy DHCP request method for non-existing option 54. ProxyDHCP request is sent to port 67 with broadcast IP address if the server identifier in option 54 is zero. Packets with source port different than BOOTPS_PORT and PXE_PORT are filtered by the PROXY • SHELL CLI is currently supported on ConnectX-3 and ConnectX-3 Pro adapter cards only • The server's IP address in DHCP server replies is now checked before checking the reply type. This will ignore NACK replies from servers which already were ignored by the client. In case of 2 DHCP servers in the same subnet, the client will eventually choose one of them, by sending the DHCP REQUEST with 'DHCP Server Identifier' (option 54) filled with the requested server's IP address. • Both the GUID and the MAC are printed on the screen when the port link layer is set as InfiniBand • PROXYDHCP and PXEBS settings are saved under netdevice settings • rootpath/filename/nextserver are now fetched from the netdevice settings • The cached DHCP packet are received only if working with the same net device. When pxelinux.0 receives the cached DHCP packet from the UNDI API, it constructs a new (fake) packet for the current net device. If the process is stopped and then restarted and booted from the next boot device which serves as the second port in the HCA, a new (fake) DHCP packet is not constructed. The previous packet which includes all the information of the first port (IP, MAC, Netmask, etc...) is used. If an old (fake) DHCP packet is discovered, its chaddr is compared to the chaddr in the pxe_netdev, if not similar, a new (fake) DHCP packet is created. • PXE shutdown is called if int22 with function 0x000C is called. • Changed DHCP discover timeouts to comply with PXE spec

Table 15 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.306	<ul style="list-style-type: none"> • Added validation script for the released ROMs • Added the option to always keep SAN hook to enable WIN install on iSCSI target • Added compilation flag around the flash readout. • Added URI Boot retry. Default retries = 0. • Added Unmap MPT command in teardown. • Added support for HII iSCSI configuration. • Added 64-bit PCI BAR support (Large bar). • Added the option added for running PXE with promiscuous VLAN. • Re-added COMBOOT image support by default. • Enabled pages-function handling in Connect-IB initialization stage to work according to the PRM. • Applied additional patches from ipxe.org • Updated the window even if ACK does not acknowledge new data. • Modified the error print to debug print. • Modified the printed string when initializing devices. • Modified the error print. Added additional information to make the output more user-friendly. • Changed the size of the domain name array to 0xfd. • Disabled the waiting period for link up on trunk-net-device when VLAN is enabled on port. • Removed unsupported EQ event in Connect-IB® • Fixed an issue for TLV with length 0. • Fixed an issue related to sync VLAN IRQ operation with trunk IRQ operation. • Fixed an issue which enabled a netdevice (VLAN) to open/close twice. • Fixed an issue which prevented the iSCSI initiator's name from being received from HII. • Fixed an issue related to dual port adapters; occasionally, booting from the second port resulted in TFTP download failure when the first port was already linked up with DHCP, and has received a TFTP address. • Fixed an issue which caused PXE boot failure when using a filename if iSCSI rootpath is set. • Fixed an issue which prevented the device to PXE boot from the 2nd port if first port was already downloaded. • Fixed compilation issue. • Fixed a broken VLAN issue. • Fixed a retry issue when the value is infinite.

Table 15 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.225	<ul style="list-style-type: none"> • Added additional information to the error print output • Added compilation flag around the flash readout • Added URI Boot retry. Default retries = 0 • Added Unmap MPT command in teardown • Added 64-bit PCI BAR support • Added an option for running PXE with promiscuous VLAN • Added support for HII iSCSI configuration • Enlarged the mailbox size to 4kb • Enlarged the number of WQE to 64 (from 4) • Enabled multiple DHCP offers to be received before proceeding to request state • Changed the size of the domain name array to 0xfd • Changed error print to debug print • Changed printed string when initializing devices • Kept the SAN connection permanently open to enable Windows install on iSCSI target even when the iSCSI target is empty • Re-added COMBOOT image support by default • Prevented a netdevice (VLAN) from opening/closing twice • Removed unsupported EQ event in Connect-IB® • Disabled the waiting time for link up on trunk net device when VLAN is enabled on a port • Fixed sync VLAN IRQ operation with trunk IRQ operation • Fixed iSCSI initiator's name retrieval from HII issue • Fixed an issue caused in dual port adapters, when the first port was already linked up with DHCP, and had received a TFTP address. Booting from the second port resulted in TFTP download failure. • Fixed retry issue when the value is infinite • Fixed a TLV with length 0 issue • Fixed a PXE boot failure issue occurred when using a filename when iSCSI rootpath is set • Fixed "Impossible to PXE boot from 2nd port if first port already downloaded." issue • Fixed compilation issue • Fixed broken VLAN support issues
Rev 3.4.151	<ul style="list-style-type: none"> • Enlarged the mailbox size to 4kb • Enlarged the number of WQE to 64 (from 4) • Enabled multiple DHCP offers to be received before proceeding to request state
Rev 3.4.146	<ul style="list-style-type: none"> • Fixed memory corruption issues • Modified TLV flash access • Added additional WQ
Rev 3.4.142	<ul style="list-style-type: none"> • Enabled firmware to handle the link state with the Subnet Manager • Updated the DHCP class code to NONE • Added flash access capability for reading software-to-software configurations • Enabled DHCP validation of MAC address and XID for a unique tuple • Improved randomness algorithm for DHCP XID

Table 15 - FlexBoot Changes and New Feature

Version	Description
Rev 3.4.112	<ul style="list-style-type: none"> • Broadcast responses for firewall support • Enabled request broadcast responses from DHCP server to support firewall.
Rev 3.4.100	<ul style="list-style-type: none"> • OCSD activation initiation change • Moved the OCSD activation initiation from the FlexBoot to the CLP code. This enables the OCSD • activation to no longer be dependent on the FlexBoot being enabled in the servers's BIOS configuration. • Messages' improvement • Made the FlexBoot on-screen notification messages more informative and user friendly. • FlexBoot and CLP merge improvement • Improved the process of merging the FlexBoot and CLP codes together. • PXE and UFI merge capability • Added the ability to merge the PXE image with a UFI image. • Supported servers • Added FlexBoot support capabilities to several new non-HP servers. • Use of newer iPXE version • Moved to use a newer iPXE version as the basis for the Flexboot release. • Fixed "no more network devices" issues during Flexboot.