



Connect. Accelerate. Outperform.™

# **Mellanox Switch-IB™ Firmware Release Notes**

Rev 11.0300.0354

## NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT (“PRODUCT(S)”) AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES “AS-IS” WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER’S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies  
 350 Oakmead Parkway Suite 100  
 Sunnyvale, CA 94085  
 U.S.A.  
[www.mellanox.com](http://www.mellanox.com)  
 Tel: (408) 970-3400  
 Fax: (408) 970-3403

© Copyright 2016. Mellanox Technologies LTD. All Rights Reserved.

Mellanox®, Mellanox logo, BridgeX®, CloudX logo, Connect-IB®, ConnectX®, CoolBox®, CORE-Direct®, EZchip®, EZchip logo, EZappliance®, EZdesign®, EZdriver®, EZsystem®, GPUDirect®, InfiniHost®, InfiniScale®, Kotura®, Kotura logo, Mellanox Federal Systems®, Mellanox Open Ethernet®, Mellanox ScalableHPC®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, NP-1c®, NP-2®, NP-3®, Open Ethernet logo, PhyX®, SwitchX®, Titera®, Titera logo, TestX®, The Generation of Open Ethernet logo, UFM®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners.

For the most updated list of Mellanox trademarks, visit <http://www.mellanox.com/page/trademarks>

# Table of Contents

<b>Table of Contents</b> .....	<b>3</b>
<b>List of Tables</b> .....	<b>4</b>
<b>Release Update History</b> .....	<b>5</b>
<b>Chapter 1 Overview</b> .....	<b>6</b>
1.1 Supported Systems .....	6
1.2 Firmware and Software Interoperability .....	6
1.3 Supported Cables and Modules .....	6
1.4 Firmware Upgrade .....	7
1.5 PRM Revision Compatibility .....	7
<b>Chapter 2 Changes and New Features in Rev 11.0300.0354</b> .....	<b>8</b>
<b>Chapter 3 Known Issues</b> .....	<b>9</b>
<b>Chapter 4 Bug Fixes History</b> .....	<b>10</b>
<b>Chapter 5 Firmware Changes and New Feature History</b> .....	<b>11</b>

## List of Tables

Table 1 -Release Update History .....	5
Table 2 -Supported Systems .....	6
Table 3 -Qualified EDR Cables .....	6
Table 4 -Firmware Rev 11.0300.0354 Changes and New Features .....	8
Table 5 -Known Issues .....	9
Table 6 -Fixed Bugs List .....	10
Table 7 -History of Major Changes and New Features .....	11

# Release Update History

*Table 1 - Release Update History*

Date	Description
February 08, 2016	First release
May 19, 2016	Updated issue number 2 in Table 5, "Known Issues," on page 9

# 1 Overview

These are the release notes for the Switch-IB™ firmware, Rev 11.0300.0354. This firmware complements the Switch-IB™ silicon architecture with a set of advanced features, allowing easy and remote management of the switch.



Firmware Rev 11.0300.0354 is compatible with MFT tools v3.8.0-56. Using older versions of MFT tools causes failure during image creation.

## 1.1 Supported Systems

This firmware supports the devices and protocols listed in [Table 2](#). For the most updated list of switches supported, visit the Firmware Download pages on Mellanox.com.

**Table 2 - Supported Systems**

Device Part Number	Description
MSB7790	Switch-IB™ based EDR InfiniBand switch; 36 QSFP28 ports; externally managed

## 1.2 Firmware and Software Interoperability

To raise links with platforms based on the following ICs, these minimum requirements must be met:

- ConnectX®-2 – firmware v2.9.1000
- ConnectX®-3 – firmware v2.31.6130
- ConnectX®-4 – firmware v12.0100.6440
- Connect-IB® – firmware v10.10.4020
- SwitchX® – firmware v9.2.7300 (or MLNX-OS v3.3.5006)

## 1.3 Supported Cables and Modules

[Table 3](#) presents the qualified EDR cables for externally managed EDR switch systems.

**Table 3 - Qualified EDR Cables**

Mellanox P/N	Description	Cable Length
MCP1600-E00A	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	0.5m
MCP1600-E001	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	1m
MCP1600-E01A	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	1.5m
MCP1600-E002	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	2m
MCP1600-E02A	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	2.5m
MCP1600-E003	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	3m

**Table 3 - Qualified EDR Cables**

Mellanox P/N	Description	Cable Length
MCP1600-E004	Mellanox® passive copper cable, up to 100Gb/s, QSFP28, LSZH	4m
MFA1A00-E005	Mellanox® active fiber cable, up to 100Gb/s, QSFP28	5m
MFA1A00-E010	Mellanox® active fiber cable, up to 100Gb/s, QSFP28	10m
MFA1A00-E015	Mellanox® active fiber cable, up to 100Gb/s, QSFP28	15m
MFA1A00-E050	Mellanox® active fiber cable, up to 100Gb/s, QSFP28	50m
MFA1A00-E100	Mellanox® active fiber cable, up to 100Gb/s, QSFP28	100m

Please refer to the LinkX™ Cables and Transceivers webpage ([www.mellanox.com](http://www.mellanox.com) → Products → Cables and Transceivers) for the full list of supported cables and transceivers.

## 1.4 Firmware Upgrade

Firmware upgrade may be performed directly from any previous version to this version. To upgrade firmware, please refer to the Mellanox Firmware Tools (MFT) package at:

[http://www.mellanox.com/page/management\\_tools](http://www.mellanox.com/page/management_tools)

## 1.5 PRM Revision Compatibility

Firmware Rev 11.0300.0354 complies with the following programmer's reference manual:

- SwitchX® Family Programmer's Reference Manual (PRM), Rev 1.15 or later

## 2 Changes and New Features in Rev 11.0300.0354

**Table 4 - Firmware Rev 11.0300.0354 Changes and New Features**

Category	Description
General	Added support for Port Mirroring
General	Improved support for adaptive routing, adaptive routing notification, fault routing, fault routing notification
Link	Removed out-of-the-box Forward Error Correction (FEC), reaching 90ns latency, on Mellanox GA level AOCs equal to or shorter than 30m. <ul style="list-style-type: none"> <li>MFA1A00-EXXX: 3, 5, 10, 15, 20, 30</li> </ul>
Link	Removed out-of-the-box FEC, reaching 90ns latency, on Mellanox GA level copper cables equal to or shorter than 2m. <ul style="list-style-type: none"> <li>MCP1600-EXXX: A, 1, 1A, 2</li> </ul>
Link	Added support for FDR10 speed
Chassis Management	Added support for power supply monitoring (for more information please refer to the MSPS register in the SwitchX Family Programmer's Reference Manual)



### 3 Known Issues

Table 5 describes known issues in this firmware release and possible workarounds.

**Table 5 - Known Issues**

Index	Category	Description	Possible Workaround
1.	General	Congestion control is not supported	N/A
2.	Configuration Management	Force FDR10 is not supported.	N/A
3.	LEDs	Switch LEDs do not blink during boot	N/A
4.	LEDs	Port LEDs do not flash on system boot.	N/A
5.	LEDs	Fan LEDs may behave unexpectedly in the first 5 seconds of system boot.	N/A
6.	Power Management	Link width reduction is not supported in this release.	N/A
7.	Interoperability	If QDR is not enabled for the switch's InfiniBand Port Speed while connected to ConnectX-3/Pro or Connect-IB® FDR adapters or to SwitchX® / SwitchX®-2 FDR switches, links will rise at SDR or DDR (even if FDR is enabled)	Enable QDR (in addition to FDR) when connecting to peer ports running at FDR
8.	Interoperability	When explicitly configuring FDR10 on Switch-IB™, the link may not rise.	To raise link with an FDR10 device, make sure all speeds, including EDR, are configured on Switch-IB.
9.	Network	Adaptive routing and adaptive routing notification do not support 3D Torus topologies.	N/A

## 4 Bug Fixes History

**Table 6 - Fixed Bugs List**

Index	Category	Description	Discovered in Release	Fixed in Release
1.	Temperature	Minimum fan speed may drop.	11.0200.0120	11.0204.0124
2.	Link	Bit error rate is not optimal on QDR links.	11.1.1002	11.0200.0118
3.	Interoperability	Only connections to Switch-IB™, ConnectX®-3, ConnectX-3 Pro, Connect-IB™, and SwitchX® family devices are supported.	11.1.1002	11.0100.0112
4.	Interoperability	Connecting a cable longer than 30m to ConnectX-3, ConnectX-3 Pro or Connect-IB platforms causes interoperability issues.	11.1.1002	11.0100.0112
5.	pLFT	Packets are lost on private linear forwarding table (pLFT).	11.1.1002	11.0100.0112
6.	Chassis Management	Port LEDs may continue to blink even after a bad cable is removed.	11.1.1002	11.0100.0112

## 5 Firmware Changes and New Feature History

**Table 7 - History of Major Changes and New Features**

Category	Description
11.0204.0124	
General	Bug fixes
11.0200.0120	
Power Management	Reduced typical system power consumption to 136W
Network	Added support for Adaptive Routing
Link	Removed forward error correction (FEC) on cables shorter or equal to 2 meters and with 12G attenuation less than 14
Release 11.0100.0112	
General	Added virtual-lane-to-virtual-lane (VL2VL) support as part of ExtendedSwitchInfo
General	Bug fixes
Release 11.1.1002	
General	This is the first firmware GA release for Switch-IB™ based EDR InfiniBand switch
General	Reduced fan speed to 60% from 100% in SB7790 switch system