

Ubuntu 16.10 Inbox Driver Release Notes

Ubuntu 16.10



NOTE:

THIS HARDWARE, SOFTWARE OR TEST SUITE PRODUCT ("PRODUCT(S)") AND ITS RELATED DOCUMENTATION ARE PROVIDED BY MELLANOX TECHNOLOGIES "ASIS" WITH ALL FAULTS OF ANY KIND AND SOLELY FOR THE PURPOSE OF AIDING THE CUSTOMER IN TESTING APPLICATIONS THAT USE THE PRODUCTS IN DESIGNATED SOLUTIONS. THE CUSTOMER'S MANUFACTURING TEST ENVIRONMENT HAS NOT MET THE STANDARDS SET BY MELLANOX TECHNOLOGIES TO FULLY QUALIFY THE PRODUCT(S) AND/OR THE SYSTEM USING IT. THEREFORE, MELLANOX TECHNOLOGIES CANNOT AND DOES NOT GUARANTEE OR WARRANT THAT THE PRODUCTS WILL OPERATE WITH THE HIGHEST QUALITY. ANY EXPRESS OR IMPLIED WARRANTIES, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT ARE DISCLAIMED. IN NO EVENT SHALL MELLANOX BE LIABLE TO CUSTOMER OR ANY THIRD PARTIES FOR ANY DIRECT, INDIRECT, SPECIAL, EXEMPLARY, OR CONSEQUENTIAL DAMAGES OF ANY KIND (INCLUDING, BUT NOT LIMITED TO, PAYMENT FOR PROCUREMENT OF SUBSTITUTE GOODS OR SERVICES; LOSS OF USE, DATA, OR PROFITS; OR BUSINESS INTERRUPTION) HOWEVER CAUSED AND ON ANY THEORY OF LIABILITY, WHETHER IN CONTRACT, STRICT LIABILITY, OR TORT (INCLUDING NEGLIGENCE OR OTHERWISE) ARISING IN ANY WAY FROM THE USE OF THE PRODUCT(S) AND RELATED DOCUMENTATION EVEN IF ADVISED OF THE POSSIBILITY OF SUCH DAMAGE.



Mellanox Technologies 350 Oakmead Parkway Suite 100 Sunnyvale, CA 94085 U.S.A. www.mellanox.com

Tel: (408) 970-3400 Fax: (408) 970-3403

© Copyright 2017. Mellanox Technologies Ltd. All Rights Reserved.

Mellanox®, Mellanox logo, Accelio®, BridgeX®, CloudX logo, CompustorX®, Connect-IB®, ConnectX®, CoolBox®, CORE-Direct®, EZchip®, EZchip logo, EZappliance®, EZdesign®, EZdriver®, EZsystem®, GPUDirect®, InfiniHost®, InfiniBridge®, InfiniScale®, Kotura®, Kotura logo, Mellanox CloudRack®, Mellanox CloudXMellanox®, Mellanox Federal Systems®, Mellanox HostDirect®, Mellanox Multi-Host®, Mellanox Open Ethernet®, Mellanox OpenCloud®, Mellanox OpenCloud Logo®, Mellanox PeerDirect®, Mellanox ScalableHPC®, Mellanox StorageX®, Mellanox TuneX®, Mellanox Connect Accelerate Outperform logo, Mellanox Virtual Modular Switch®, MetroDX®, MetroX®, MLNX-OS®, NP-1c®, NP-2®, NP-3®, NPS®, Open Ethernet logo, PhyX®, PlatformX®, PSIPHY®, SiPhy®, StoreX®, SwitchX®, Tilera®, Tilera logo, TestX®, TuneX®, The Generation of Open Ethernet logo, UFM®, Unbreakable Link®, Virtual Protocol Interconnect®, Voltaire® and Voltaire logo are registered trademarks of Mellanox Technologies, Ltd.

All other trademarks are property of their respective owners .

For the most updated list of Mellanox trademarks, visit http://www.mellanox.com/page/trademarks

Mellanox Technologies 2



Table of Contents

able of Contents	3				
ist Of Tables					
napter 1 Overview	5				
1.1 Supported HCAs Firmware Versions	5				
napter 2 Known Issues	6				



List Of Tables

Table 1:	Supported Uplinks to Servers	5
Table 2:	Supported HCAs Firmware Versions	5
Table 3:	Known Issues	6



1 Overview

These are the release notes of Ubuntu 16.10 Inbox Driver. This document provides instructions on drivers for Mellanox Technologies ConnectX® based adapter cards with Ubuntu 16.10 Inbox Driver environment.

This version supports the following uplinks to servers:

Table 1 - Supported Uplinks to Servers

Uplink/HCAs	Uplink Speed
ConnectX®-4	Ethernet: 1GigE, 10GigE, 25GigE, 40GigE, 50GigE, 56GigE ^a , and 100GigE
ConnectX®-4 Lx	Ethernet: 1GigE, 10GigE, 25GigE, 40GigE, and 50GigE
Connect-IB®	InfiniBand: SDR, QDR, FDR10, FDR
ConnectX®-3/ConnectX®-3 Pro	 InfiniBand: SDR, QDR, FDR10, FDR Ethernet: 10GigE, 40GigE and 56GigE^a

a. 56GbE is a Mellanox propriety link speed and can be achieved while connecting a Mellanox adapter cards to Mellanox SX10XX switch series or connecting a Mellanox adapter card to another Mellanox adapter card.

1.1 Supported HCAs Firmware Versions

Ubuntu 16.10 Inbox Driver Ubuntu 16.10 supports the following Mellanox network adapter cards firmware versions:

Table 2 - Supported HCAs Firmware Versions

НСА	Recommended Firmware Rev.	Additional Firmware Rev. Supported
Connect-IB®	10.16.1006	N/A
ConnectX®-4 Lx	14.17.2020	N/A
ConnectX®-4	12.17.2020	N/A
ConnectX®-3 Pro	2.40.5000	N/A
ConnectX®-3	2.40.5000	N/A



2 Known Issues

The following table describes known issues in this release and possible workarounds..

Table 3 - Known Issues

Internal Ref.	Description
742682	Description: Missing "srptools" packages in ppc64le architecture.
	WA: N/A
	Keywords: stptools
554392	Description: RDMA and IB drivers need to be loaded manually after boot.
	WA: Install an RDMA service: 1. apt install software-properties-common 2. add-apt-repository ppa:talat-b87/rdmappa 3. apt-get update 4. apt-get install rdma 5. systemctl start rdma.service Keywords: RDMA and IB drivers, Manual loading
684897	Description: On rare occasions, ConnectX-3 linkup takes longer than expected, resulting in delay of link-local address generation and DHCP client failure.
	WA: Add 11-attempts 120 to the network interface configuration file.
	Keywords: IPv6 address, VLAN, ifdown/ifup interface